Update: Vehicles with milled brake fluid reservoir cover - Stop Sale and Recall

option codes 796, 797, 798, 799, 79G, 79H, 79I, 79J, 79K

NHTSA STATEMENT

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motorcycle covered by this notification until the repair has been performed. This means that dealers may not legally deliver new motorcycles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act. You should not sell, lease or deliver any Certified Pre-Owned or used motorcycles subject to a safety recall until the repair is completed. Follow any special instructions that we provide to you for the return or disposition of recall parts.

Recall 20V-166

This Stop Sale is also a Recall due to a non-compliance with NHTSA regulations.

Please be advised that replacement milled brake fluid reservoir covers will not be available for an estimated 8-10 weeks.

Vehicles that are marked with the special defect code STOP340005 are subject to a delivery stop. Models included are R nineT, R 1250 R and R 1250 GS/GSA that were produced with a milled brake fluid reservoir cover (option codes 796, 797, 798, 799, 79G, 79H, 79I, 79J, 79K), which may not fully conform to legal requirements.

Vehicles can still be sold/delivered if the cover is replaced with a non-milled (standard) original BMW brake fluid reservoir cover which will bring the vehicle into compliance. The standard cover and 2FRU should be claimed using defect code 85 99 00 37 MY. The repair order number must be entered in the RDR override. New vehicles should only be updated with the standard cover when retailed, please do not update unsold vehicles.

In addition, we are updating a small number of bikes at the warehouse with the standard cover so they can be delivered to dealers who are waiting for these units

In both cases, BMW Motorrad USA will track these vehicles and customers will be included in the recall mailing once parts are available to have the new milled brake fluid reservoir cover installed. Any vehicles you have remaining in inventory will need to be updated at that time.

Recall 20E-013:

A small number of customers may have purchased a milled cap over the counter as an accessory. Please check your records to determine if a customer has purchased a milled cap from your dealership. If you have a record with customer contact information, when parts are available, you will need to contact the customer to provide them the updated part. A copy of the customer letter will be provided to you in the near future to aid in this process.

Further updates will be provided when new milled covers are available.

Aftersales, Motorrad Dealer Direct, Recalls