

September 2021
FL856A-J
NHTSA #20V-404

Subject: FCCC Motorhome Chassis Rear PDMs

Models Affected: Specific Model Year 2016-2020 Freightliner Custom Chassis X-Line chassis manufactured November 23, 2015, through June 3, 2019, and equipped with a certain PDM.

General Information

Daimler Trucks North America LLC (DTNA), on behalf of its wholly owned subsidiary, Freightliner Custom Chassis Corporation, has decided that a defect that relates to motor vehicle safety exists on the vehicles mentioned above.

On certain chassis, the rear marker lights, brake lights, or left turn signal lights may cease to function while driving. Brake lights that do not function correctly may not notify motorists of a braking event, which may increase the risk of a crash.

Power Distribution Modules (PDMs) will be inspected and replaced as needed.

There are approximately 16,782 vehicles involved in this campaign.

Additional Repairs

Dealers must complete all outstanding Recall and Field Service campaigns prior to the sale or delivery of a vehicle. A Dealer will be liable for any progressive damage that results from its failure to complete campaigns before sale or delivery of a vehicle.

Owners may be liable for any progressive damage that results from failure to complete campaigns within a reasonable time after receiving notification.

Work Instructions

Please refer to the attached work instructions. Prior to performing the campaign, check the vehicle for a completion sticker (Form WAR260).

NOTE: If necessary, call FCCC for assistance on location of the PDM FCCC CAC (800) 206-3519

Replacement Parts

Replacement parts are now available and can be obtained by ordering the part number(s) listed below from your facing Parts Distribution Center.

If our records show your dealership has ordered any vehicle(s) involved in campaign number FL856, a list of the customers and vehicle identification numbers will be available on DTNAConnect. Please refer to this list when ordering parts for this recall.

Table 1 - Replacement Parts for FL856

| Campaign Number | Part Number | Part Description | Qty. |
|-----------------|---------------|--------------------------------------|------|
| FL856A | A66-05172-000 | MODULE-POWER DIST ASSY,CUM,X | 1 ea |
| FL856B | A66-05172-001 | MODULE-POWER DIST,ASSY,CUM,AUX,X | 1 ea |
| FL856C | A66-05172-002 | MODULE-POWER DIST, ASSY, CUM,AIR LVL | 1 ea |
| FL856D | A66-05172-004 | MODULE-POWER DIST,ASSY,ISX,XCP | 1 ea |
| FL856E | A66-05172-005 | MODULE-POWER DIST,ASSY,CUM,GRID,X | 1 ea |
| FL856F | A66-05172-006 | MODULE-POWER DIST,ASSY,ISX,XCP,NMR | 1 ea |
| FL856G | A66-05172-008 | PWR DIST MOD,ASSY,DDC,AUX,X | 1 ea |
| FL856H | A66-05172-009 | PWR DIST MOD,ASSY,DD13,X | 1 ea |
| FL856I | A66-05172-010 | POWER DIST MOD,ASSY,CUM,X | 1 ea |
| FL856J | A66-05172-011 | POWER DIST MOD,ASSY,CUM,AUX,X | 1 ea |
| FL856A-J | WAR260 | BLANK COMPLETION STICKER | 1 ea |

Table 1

September 2021
FL856A-J
NHTSA #20V-404

Removed Parts

U.S. and Canadian Dealers, please follow Warranty Failed Parts Tracking shipping instructions for the disposition of all removed parts. Export distributors, please destroy removed parts unless otherwise advised.

Labor Allowance

Table 2 - Labor Allowance

| Campaign Number | Procedure | Time Allowed (hours) | SRT Code | Corrective Action |
|-----------------|---|----------------------|-----------|---------------------------|
| FL856A-J | Inspect Rear PDM | 0.2 | 996-R111A | 06-Inspect |
| | Inspect & Replace Rear PDM | 0.4 | 996-R111B | 12-Repair Recall/Campaign |
| | Inspect & Replace Rear PDM, Call for PDM location assistance | 0.9 | 996-R111C | 12-Repair Recall/Campaign |

Table 2

IMPORTANT: When the Recall has been completed, locate the base completion label in the appropriate location on the vehicle, and attach the red completion sticker provided in the recall kit (Form WAR260). If the vehicle does not have a base completion label, clean a spot on the appropriate location of the vehicle and first attach the base completion label (Form WAR259). If a recall kit is not required or there is no completion sticker in the kit, write the recall number on a blank sticker and attach it to the base completion label.

Claims for Credit

You will be reimbursed for your parts, labor, and handling (landed cost for Export Distributors) by submitting your claim through the Warranty system within 30 days of completing this campaign. Please reference the following information in OWL:

- Claim type is **Recall Campaign**.
- In the Campaign field, enter the campaign number and appropriate condition code (e.g. **FL856-A, FL856-B, etc.**).
- In the Primary Failed Part Number field, enter **25-FL856-000**.
- In the Parts field, enter the appropriate part number(s) as shown in the Replacement Parts Table.
- In the Labor field, first enter the appropriate SRT from the Labor Allowance Table. Administrative time will be included automatically as SRT 939-6010A for 0.4 hours for RVs.
- **Removed PDMs will be returned following Warranty Failed Parts Tracking shipping instructions for the disposition of all removed parts.**
- The VMRS Component Code is **F99-999-005** and the Cause Code is **A1 - Campaign**.
- **U.S. and Canada -- Reimbursement for Prior Repairs.** When a customer asks about reimbursement, please do the following:
 - Accept the documentation of the previous repair.
 - Make a brief check of the customer's paperwork to see if the repair may be eligible for reimbursement. (See the "Copy of Owner Letter" section of this bulletin for reimbursement guidelines.)
 - Submit an OWL Recall Pre-Approval Request for a decision.
 - Include the approved amount on your claim in the Other Charges section.
 - Attach the documentation to the pre-approval request.
 - If approved, submit a based on claim for the pre-approval.
 - Reimburse the customer the appropriate amount.

**September 2021
FL856A-J
NHTSA #20V-404**

IMPORTANT: OWL must be viewed prior to performing the recall to ensure the vehicle is involved and the campaign has not been previously completed. Also, check for a completion sticker prior to beginning work.

U.S. and Canadian dealers, contact the Warranty Campaigns Department via Web inquiry at DTNACconnect.com / WSC, if you have any questions or need additional information. Export distributors, submit a Web inquiry or contact your International Service Manager.

U.S. and Canadian Dealers: To return excess kit inventory related to this campaign, U.S. dealers must submit a Parts Authorization Return (PAR) to the Memphis PDC. Canadian dealers must submit a PAR to their facing PDC. All kits must be in resalable condition. PAR requests must include the original purchase invoice number. Export Distributors: Excess inventory is not returnable.

The letter notifying U.S. and Canadian vehicle owners is included for your reference.

Please note that the National Traffic and Motor Vehicle Safety Act, as amended (Title 49, United States Code, Chapter 301), requires the owner's vehicle(s) be corrected within a reasonable time after parts are available to you. The Act states that failure to repair a vehicle within 60 days after tender for repair shall be prima facie evidence of an unreasonable time. However, circumstances of a particular situation may reduce the 60 day period. Failure to repair a vehicle within a reasonable time can result in either the obligation to (a) replace the vehicle with an identical or reasonably equivalent vehicle, without charge, or (b) refund the purchase price in full, less a reasonable allowance for depreciation. The Act further prohibits dealers from selling a vehicle unless all outstanding recalls are performed. Any lessor is required to send a copy of the recall notification to the lessee within 10 days. Any subsequent stage manufacturer is required to forward this notice to its distributors and retail outlets within five working days.

September 2021
FL856A-J
NHTSA #20V-404

Copy of Notice to Owners

Subject: FCCC Motorhome Chassis Rear PDMs

For the Notice to U.S. Customers: This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. **For the Notice to Canadian Customers:** This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Daimler Trucks North America LLC (DTNA), on behalf of its wholly owned subsidiary, Freightliner Custom Chassis Corporation, has decided that a defect that relates to motor vehicle safety exists on specific Model Year 2016-2020 Freightliner Custom Chassis X-Line chassis manufactured November 23, 2015, through June 3, 2019, and equipped with a certain PDM.

On certain X-Line multiplexed chassis, the rear marker, brake lights, or left turn signal lights may cease to function while driving. Brake lights that do not function correctly may not notify motorists of a braking event, which may increase the risk of a crash.

Rear Power Distribution Modules (PDMs) will be inspected and replaced as needed. Repairs will be performed by Daimler Trucks North America authorized service repair facilities.

Please contact an authorized Daimler Trucks North America dealer to arrange to have the Recall performed and to ensure that parts are available at the dealership. To locate an authorized dealer, go to www.Daimler-TrucksNorthAmerica.com. On the menu tab, select "Contact," scroll down to "Find a Dealer," and select the appropriate brand. The Recall will take approximately one hour and will be performed at no charge to you. You may also confirm your vehicle's involvement in this recall at this URL:
<https://dtna-dlinfo.prd.freightliner.com:48518/VinLookup/vin-module/getVinLookupPage>

You may be liable for any progressive damage that results from your failure to complete the Recall within a reasonable time after receiving notification.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days. If you have paid to have this recall condition corrected prior to this notice, you may be eligible to receive reimbursement. Please see the reverse side of this notice for details.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com. **For the Notice to U.S. Customers:** If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>. **For the Notice to Canadian Customers:** If you wish to submit a complaint about this recall, you can contact Transport Canada road safety, 80 rue Noel, Gatineau, Quebec J8Z 0A1 or call (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure

September 2021
FL856A-J
NHTSA #20V-404

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already **paid** to have this recall condition corrected you may be eligible to receive reimbursement.

Requests for reimbursement may include parts and labor. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Daimler Trucks North America LLC dealer. The following documentation must be presented to your dealer for consideration for reimbursement.

Please provide original or clear copies of all receipts, invoices, and repair orders that show:

- The name and address of the person who paid for the repair
- The Vehicle Identification Number (VIN) of the vehicle that was repaired
- What problem occurred, what repair was done, when the repair was done
- Who repaired the vehicle
- The total cost of the repair expense that is being claimed
- Proof of payment for the repair (such as the front and back of a cancelled check or a credit card receipt)

Reimbursement will be made by check from your Daimler Trucks North America LLC dealer.

Please speak with your Daimler Trucks North America LLC authorized dealer concerning this matter.

September 2021
FL856A-J
NHTSA #20V-404

Work Instructions

Subject: FCCC Motorhome Chassis Rear PDMs

Models Affected: Specific Model Year 2016-2020 Freightliner Custom Chassis X-Line chassis manufactured November 23, 2015, through June 3, 2019, and equipped with a certain PDM.

PDM Inspection and Replacement

1. Check the base label (Form WAR259) for a completion sticker for FL856 (Form WAR260) indicating this work has been completed. The base label is usually located on the front wall under the dash. If a sticker is present, no further work is needed. If there is no sticker, proceed with the next step.
2. Park the vehicle on a level surface, shut down the engine, and set the parking brake. Chock the tires.

NOTE: If necessary, call FCCC for assistance on location of the PDM. FCCC CAC (800) 206-3519

3. Locate the serial number on the side of the PDM. If the serial number is equal to, or less than, 18106398, go to the next step. If serial number is greater than 18106398, go to step 10.
4. Disconnect the chassis battery ground cable from the battery.

NOTE: Not all of the PDM electrical connections will be used.

5. Disconnect all electrical connections to the PDM. See [Fig. 1](#).




Fig. 1, PDM Components

**September 2021
FL856A-J
NHTSA #20V-404**

6. Remove the mounting fasteners attaching the PDM to the chassis and remove the PDM.

IMPORTANT: When replacing the PDM, remove the cover from the new PDM and compare the fuse and relay configurations with the PDM being replaced. Body builders may have added optional fuses and relays after the chassis was built. If this is the case, make certain to remove and reinstall the additional fuses and relays in the same location on the new PDM and replace the cover.

7. Using the mounting fasteners removed earlier, attach the PDM to the chassis.

8. Connect all electrical connections to the PDM.

9. Connect the chassis battery ground cable to the battery.

10. Clean a spot on the base label (Form WAR259). Write the recall number, FL856, on a blank red completion sticker (Form WAR260), and attach it to the base label to indicate this recall has been completed.