

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers– U.S. and Canada
Western Star and Sterling Dealers– U.S. and Canada
FCCC Dealers– U.S. and Canada
ThomasBuiltBusesDealers– U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Detroit Diesel Distributors
Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT
P.O. Box 4090 800-547-0712
Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the **WSC Link on DTNAConnect**

REF #: ICI21-010
Effective: 4/14/21
Release: 4/14/21

SUBJECT: FL860 - Revised Bulletin

This letter is to inform you that a revised bulletin for Recall FL860 Freightliner Engine Harness Clearance is available on DTNAConnect. Please print and use the revised bulletin for all work under FL860 from this point forward.

REVISION: The torque value on step 2.3 of page 13 of the work instructions has been updated.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

For your reference, a French translation of ICI21-010 is on the next page.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.

Daimler Trucks North America LLC

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers– U.S. and Canada
Western Star and Sterling Dealers– U.S. and Canada
FCCC Dealers– U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Export Distributors

WARRANTY CAMPAIGNS DEPARTMENT
P.O. Box 4090 800-547-0712
Portland

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link](#) on [DTNAConnect](#)

REF #: ICI21-010

Effective: 4/14/21

Release: 4/14/21

SUBJECT: FL860 - Revised Bulletin

Cette lettre a pour but de vous informer qu'une version révisée du bulletin de rappel du jeu de faisceau moteur Freightliner FL860 est disponible sur DTNAConnect. Veuillez imprimer et utiliser le bulletin révisé pour tous les travaux sous FL860 à partir de ce pointez en avant.

RÉVISION: La valeur de couple à l'étape 2.3 de la page 13 des instructions de travail a été mise à jour

Si vous avez des questions ou avez besoin de plus amples informations, contactez le service des campagnes de garantie en soumettant une demande via le lien WSC sur DTNAConnect.

Pour votre information, une traduction française de ICI21-010 se trouve à la page suivante.

I
M
P
O
R
T
A
N
T

C
A
M
P
A
I
G
N

I
N
F
O
R
M
A
T
I
O
N