

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
 Freightliner Dealers – U.S. and Canada
 Western Star and Sterling Dealers – U.S. and Canada
 FCCC Dealers – U.S. and Canada
 Direct Warranty Customers – U.S. and Canada
 Export Distributors

Daimler Trucks North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the **WSC Link on DTNAConnect**

REF #: ICI25-019

Effective: 07/31/25

Release: 07/31/25

SUBJECT: FL863AB – Third Revised Bulletin

This letter is to inform you that a third revised bulletin for Final Recall FL863AB Freightliner Cascadia Brake Light Illumination is available on DTNAConnect. Please print and use the revised bulletin for all work under FL863 from this point forward.

THIRD REVISION: A note has been added regarding the updated brake light switch (12-31616-000), which now requires two harnesses for proper connection between the dash harness and the switch.

- Harness A66-23212-000 connects the dash harness to a 2-pin connector.
- Harness A66-23214-000 connects the 2-pin connector to the brake light switch.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAConnect.

REF #: ICI25-019

En vigueur:: 31/07/25

Date de sortie:: 31/07/25

OBJET: FL863AB – Troisième bulletin révisé

Cette lettre a pour but de vous informer qu'un troisième bulletin révisé concernant le rappel final FL863AB du feu de freinage Freightliner Cascadia est disponible sur DTNAConnect. Veuillez imprimer et utiliser ce bulletin révisé pour tous les travaux relevant du FL863 à partir de maintenant.

TROISIÈME RÉVISION: Une note a été ajoutée concernant l'interrupteur de feu stop mis à jour (12-31616-000), qui nécessite désormais deux faisceaux pour une connexion correcte entre le faisceau du tableau de bord et l'interrupteur.

- Le faisceau A66-23212-000 relie le faisceau du tableau de bord à un connecteur à 2 broches.
- Le faisceau A66-23214-000 relie le connecteur à 2 broches au contacteur de feu stop.

Si vous avez des questions ou avez besoin de plus amples informations, contactez le service des campagnes de garantie par soumettre une demande à l'aide de l'application Garantie Support Center (WSC), située sur le DTNA Portal.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.