

David J. Johnson Director Service Engineering Operations Ford Customer Service Division Ford Motor Company P. O. Box 1904 Dearborn, Michigan 48121

December 22, 2020

## TO: All U.S. Ford and Lincoln Dealers

## SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD Safety Recall 20S57 Certain 2020 Model Year F-350 Chassis Cab Vehicles built with 7.3L Gas Engine and Ambulance Package Wide Track Rear Axle Update

## AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
F-350	2020	Kentucky	December 16, 2019 through September 16, 2020

Affected vehicles are identified in OASIS and FSA VIN Lists.

## REASON FOR THIS SAFETY RECALL

The affected vehicles were ordered with Ambulance Package and "Wide Track" Rear Axle, however, were built with a Standard Rear Axle. Depending on the body installed by the body builder, clearance to the inner Dual Rear Wheel tire may be below the minimum clearance required. This could cause tire contact with the second unit body. The subsequent tire damage could result in tire blowout which may increase loss of vehicle control on these emergency vehicle applications.

## SERVICE ACTION

Before demonstrating or delivering any new in-stock vehicles involved in this recall, dealers are to update vehicle with "Wide Track" Rear Axle per technical instructions. This service must be performed on all affected vehicles at no charge to the vehicle owner.

## **OWNER NOTIFICATION MAILING SCHEDULE**

Owner letters are expected to be mailed the week of January 11, 2021. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

## PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

#### **ATTACHMENTS**

Attachment I:Administrative InformationAttachment II:Labor Allowances and Parts Ordering InformationAttachment III:Technical InformationOwner Notification Letters

## **QUESTIONS & ASSISTANCE**

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

Pf Johnson

David J. Johnson

### NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Safety Recall 20S57

Certain 2020 Model Year F-350 Chassis Cab Vehicles built with 7.3L Gas Engine and Ambulance Package Wide Track Rear Axle Update

#### **OASIS ACTIVATION**

OASIS was activated on October 1, 2020

### FSA VIN LISTS ACTIVATION

FSA VIN Lists were made available through <u>https://web.fsavinlists.dealerconnection.</u>com on October 1, 2020. Owner names and addresses will be available by week of January 25, 2021.

**NOTE:** Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

## SOLD VEHICLES

- Ford has not issued instructions to stop selling/delivering or driving used vehicles under this safety recall. Owners should contact their dealer for an appointment to have their vehicles remedied as soon as practicable. Owners can continue to safely drive their vehicles. Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

## STOCK VEHICLES

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

#### DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

#### TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this recall.

#### OWNER REFUNDS

Refunds are not approved for this program.

#### **RENTAL VEHICLES**

Rental vehicles are not approved for this program.

## NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Safety Recall 20S57

Certain 2020 Model Year F-350 Chassis Cab Vehicles built with 7.3L Gas Engine and Ambulance Package Wide Track Rear Axle Update

# ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSA's / Related Damage.
- For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required, although related damage must be on a separate repair line with the "Related Damage" radio button checked.
  - Ford vehicles 3 years or 36,000 miles

## **CLAIMS PREPARATION AND SUBMISSION**

- **Claim Entry**: Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
  - When entering claims, select claim type 31: Field Service Action. The FSA number 20S57 is the sub code.
  - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- **Related Damage/Additional labor and/or parts**: Must be claimed as Related Damage on a separate repair line from the FSA with same claim type and sub code as described in Claim Entry above.

**IMPORTANT:** Click the Related Damage Indicator radio button.

#### **ATTACHMENT II**

Page 1 of 2

## NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Safety Recall 20S57

Certain 2020 Model Year F-350 Chassis Cab Vehicles built with 7.3L Gas Engine and Ambulance Package

Wide Track Rear Axle Update

#### LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Remove and Install Rear Axle, Build Axle / Check Set Clearances	MT20S57B	M Time up to 7.5 Hours

### PARTS REQUIREMENTS / ORDERING INFORMATION

Part Number	ort Number Description		Claim Quantity
HC3Z-4010-N	Axle Housing	1	1
HC3Z-4234-G	Left Axle Shaft	1	1
HC3Z-4234-J	Right Axle Shaft	1	1
F81Z-1001-AA	Axle Shaft O-rings (1 per pkg, 2 req)	2	2
HC3Z-00813-A	Axle bolts (1 per pkg, 16 req)	16	16
HC3Z-1S175-B	C3Z-1S175-B Hub Seals (1 per pkg, 2 req)		2
HC3Z-4676-A	Pinion Seal (1 per pkg, 1 req)	1	1
HC3Z-00810-A	Thrust Washer – Tail Bearing (1 per pkg, 1 req)	1	1
HC3Z-383609-A	Pinion Nut Washer (1 per pkg, 1 req)	1	1
HC3Z-00811-A	Pinion Nut (1 per pkg, 1 req)	1	1
HC3Z-4662-B	Spacer – Collapsible (1 per pkg, 1 req)	1	1
HC3Z-4630-B	Bearing Cone – Pinion Head (1 per pkg, 1 req)	1	1
HC3Z-4628-B	Bearing Cup – Pinion Head (1 per pkg, 1 req)	1	1
HC3Z-4561-C	Bearing Cone – Pinion Tail (1 per pkg, 1 req)	1	1
HC3Z-4616-B	Bearing Cup – Pinion Tail (1 per pkg, 1 req)	1	1
XY-80W90-QL	Axle Fluid (3.37I needed)	4	4
XL-3	Friction Modifier	1	1
E4HZ-4A254-A	U-Joint Straps (1 per pkg,2 req)	2	2
F1HZ-4N272-A	U-Joint Bolts (1 per pkg, 4 req)	4	4
HC3Z-00812-B	Rear Caliper Bracket Bolts (4 per pkg, 8 req)	2	8
W500764-S439	/500764-S439 Shock Absorber Nuts (4 per pkg, 2 req)		2
W520115-S440	520115-S440 Shock Absorber Bolts (4 per pkg, 2 req)		2
HC3Z-5705-H	U-Bolts (1 per pkg, 4 req)	4	4
W711310-S441	U-Bolt Nuts (4 per pkg, 8 req)	2	8

Order your parts through normal order processing channels. To guarantee the shortest delivery time, an emergency order for parts must be placed.

#### NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Safety Recall 20S57

Certain 2020 Model Year F-350 Chassis Cab Vehicles built with 7.3L Gas Engine and Ambulance Package Wide Track Rear Axle Update

#### DEALER PRICE

For latest prices, refer to DOES II.

#### PARTS RETENTION, RETURN, & SCRAPPING

Follow the provisions of the Warranty and Policy Manual, Section 1 - WARRANTY PARTS RETENTION AND RETURN POLICIES. If a replaced part receives a scrap disposition, the part must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall.

#### EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

# CERTAIN 2020 F-350 CHASSIS CAB VEHICLES BUILT WITH 7.3L GAS ENGINE AND AMBULANCE PREP PACKAGE — WIDE TRACK REAR AXLE UPDATE

# SERVICE PROCEDURE

NOTE: Order parts per dealer bulletin, only the ring, pinion and carrier will be reused in new housing.

- 1. Remove the axle assembly from the vehicle. Please follow the Workshop Manual (WSM) procedures in Section 205-02B.
- 2. Remove the differential carrier assembly and axle shafts from the axle assembly. Please follow the WSM procedures in Section 205-02B.
- 3. Install the differential carrier assembly and *new* axle shafts onto the *new* axle assembly. Please follow the WSM procedures in Section 205-02B.
- 4. Install the new Axle Assembly to the vehicle. Please follow the WSM procedures in Section 205-02B.
- IMPORTANT NOTE: Federal law prohibits selling motor vehicle parts or components that are under safety, compliance, or emissions recall. Unless a part is requested to be returned to Ford, all parts replaced under this FSA must be scrapped in accordance with all applicable local, state and federal environmental protection and hazardous material regulations. Refer to the Parts Retention, Return, & Scrapping section of the FSA dealer bulletin for further information.

