

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6101
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 28, 2022

Subject: REVISION: N202308930-02 – Safety Recall
Rear Suspension Toe Link May Break
Revised Service Procedure

Models: 2010 – 2013 Buick LaCrosse
2012 – 2013 Buick Regal
2013 Chevrolet Malibu

To: All General Motors Dealers

This bulletin is being revised to update the Service Procedure. Please discard all previous copies of N202308930.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS