

**Campaign code:**

L73X-R.02.20

**Campaign Name:**

Internal door handle replacement

**Model:**

Aventador

**Model year:**

MY 20

**Special or limited editions:**

All versions

**Markets:**

All except South Korea and Japan

**VIN identification:**

From LLA09410 to LLA09522

**Important:** before proceeding with the repair, connect to the warranty portal and use VIN Info to check that

- The vehicle is actually affected by the instructions given in this bulletin; some vehicles may not be, even when their VIN is included.
- Procedures are identified by a letter (e.g. A, B or C....etc., whose differences will be explained later in this bulletin); make sure that the spare parts corresponding to the assigned procedure are used.

**Example**

Code	Type	Description	Bulletin	Proc.
LXX-A.XX.XX		CAMPAIGN NAME		B

**NOTE:**

Procedure A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

**Network information notice:**

As a result of continuous product monitoring, Automobili Lamborghini S.p.A. requires the replacement of the left and right internal door handle due to a possible incorrect installation.

**Operations:**

The following instructions include the steps:

- Step B: Internal door handle replacement

**Solutions for the network:**

Update the car as stated in the instructions.

**Replacement parts:****IMPORTANT!**

When the VIN is entered in the LIASS system, the specific operation to be performed on that vehicle will be specified. On the basis of the operation displayed on LIASS, please order one of the following codes associated with the operations concerned, where suggested:

**Operation B:**

P/N Kit	Description	Q
470800345	The kit contains: - 1 X DOOR HANDLE,INNER; P/N: 470837293C - 1 X DOOR HANDLE,INNER; P/N: 470837294C - 2 X ROLL PIN; P/N: N0133481	1



**Management of replaced parts:**

Store properly and tagged the parts replaced with bar code form for their identification during Area Manager visits.

**Labour:**

- Step B:1 h



**NOTE:**

The time was increased by half an hour due to the necessary attention regarding the safety Recall.


**Bulletins superseded:**

None.

**Warranty instructions:**

To request reimbursement for the corrective action performed, access the Warranties section of the Lamborghini Portal and follow the "Campaigns" entry instructions in the W.Claim manual which can be downloaded from the Portal.

Select the required campaign and proceed with entry, carefully reading the options present in the alert displayed by the system (see example) and select the option performed on the vehicle.



Depending on the option performed, the reimbursement will be structured in the following manner:

- OPTION B - Internal door handle replacement



**WARNING!**

Attach all documents generated during the work carried out as evidence of the work itself, for instance workshop orders, diagnostic protocols etc. If one or more of these is missing it may lead to a rejected reimbursement request.

Fill out the Service and Recall Campaign section in the warranty booklet, which is shown in the figure below.

**Tools/Materials required**

Cod.	Description	Q
n/n	n/n	0



**Work instructions:**

1. To replace the left and right internal door handle, perform the instructions given in the Workshop Manual at the following paths:

08 Body → 68 Interior trim → G - Interior door handle, left → Disassembly/Assembly

08 Body → 68 Interior trim → H - Interior door handle, right → Disassembly/Assembly



**IMPORTANT:**

*The documents which must be provided with the warranty request are:*

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

*Failure to follow these procedures could lead to the request being rejected.*