

SIB 71 01 20

RECALL 20V-514:TIRE PRESSURE LABEL

This Service Information Bulletin (Revision 2) replaces SI B71 01 20 dated August 2020.

What's New:

- Parts Information
- Warranty

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

For centers that qualify, this Recall repair is eligible to be performed via Mobile Assistance.

MODEL

E-Series	Model Description	Production Date
G07	X7 Sports Activity Vehicle	June 17, 2020 – August 12, 2020

AFFECTED VEHICLES

Affected vehicles which require this Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA NEXT or Warranty Vehicle Inquiry.

SITUATION

BMW AG is conducting a Voluntary Non-Compliance Recall (effective August 20, 2020) on certain Model Year 2021 BMW X7 SAV models that were produced between June 17, 2020 and August 12, 2020.

The tire pressure label may contain incorrect information regarding tire size. Therefore, it may not meet a Federal requirement.

The Recall Notice and Q&A have been attached for further information.

CAUSE

RENSEIGNEMENTS SUR LES PNEUS ET LE CHARGEMENT SEATING CAPACITY TOTAL 7 FRONT 2 REAR 5 NOMBRE DE PLACES TOTAL 7 AVANT 4 ARRIERE The combined weight of the occupants and cargo should never exceed Le polds total des occupants et du chargement ne doit jamais dépasser 548 kg ou 1208 lbs.				5 A20 631
TIRE/PNEU	SIZE DIMENSIONS	COLD TIRE PRESSURE PRESSION DES PNEUS A FRIOD	SEE OWNER'S MANUAL FOR ADDTIONAL	
FRONT/AVANT	255/55 R 20 XL	240 KPA, 35 PSI	INFORMATION VOIR LE MANUEL DE	
REAR/ARRIERE	255/55 R 20 XL	290 KPA, 42 PSI	L'USAGER POUR PLUS	
SPARE DE SECOURS	NONE	NONE KPA, NONE PSI	DE RENSEIGNEMENTS	

During vehicle production, a tire pressure label containing the incorrect tire size was installed on the vehicle's driver side "B" pillar.

The tire pressure label displays an incorrect tire size of 20 inches instead of the correct tire size.

CORRECTION

Replace the tire pressure label with one showing the correct tire size for the vehicle equipment.

PROCEDURE

Remove the tire pressure label from the driver's side B-pillar.

- Carefully use a heat gun to soften the adhesive backing on each label
- Remove the label with a plastic wedge

Copyright ©2020 BMW of North America, Inc.

Remove all adhesive residue from the B-pillar with an appropriate cleaner (e.g., brake cleaner, rubbing alcohol) and install new tire label.

PARTS INFORMATION

Please create an IDS Ticket – Parts logistics – Coded Parts RDC – Coded Parts RDC Complete the information and submit.

The forms can be electronically created at: Create ticket– Parts logistics – Coded Parts RDC-Forms

Part Number	Description	Quantity
71 24 6 781 271	Tire pressure label	1

WARRANTY INFORMATION

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below and the coded part number listed above:

Defect Code: 0071760200

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop-

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 69 876	Replace the tire pressure label	3 FRU

Or:

The vehicle arrives at your center and this Recall shows open (No other main work will be performed or claimed during this workshop visit)-

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 2	00 69 326	Replace the tire pressure label	5 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B71 01 20 WP 1), unless otherwise required by State law.

Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

Based on the issue and age of the Affected Vehicles being addressed by this Safety Recall Campaign, a reimbursement request for a qualifying prior customer-pay repair is not likely.

However, if you receive a reimbursement request from a customer for a prior repair that may qualify, please contact the Warranty department (include a legible copy of the invoice) through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections. The Warranty department will review and respond to your inquiry accordingly.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin	
	Copyright ©2020 BMW of North America, Inc.	

71 01 20_RECALL 20V-514:TIRE PRESSURE LABEL

Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Parts Department

Powered by Froala Editor

Supporting Materials

picture_as_pdf B710120 Recall Notice.pdf picture_as_pdf B710120_2020-BMW-MY2021-G07-TirePressureLabel-FAQ-(20Aug2020).pdf

NON-COMPLIANCE RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 20V-514: Tire Pressure Label – B71 01 20

BMW AG is conducting a Voluntary Non-Compliance Recall (effective August 20, 2020) on certain Model Year 2021 BMW X7 SAV models that were produced between June 17, 2020 and August 12, 2020.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

Non-Compliance Recall 20V-514 Tire Pressure Label Model Year 2021 BMW X7 SAV Issue Date: 08/20/2020 Last Update: 08/20/2020

Q1. Which BMW models in the US are potentially affected by this Non-Compliance Recall?

Certain Model Year 2021 BMW X7 SAV models in the US, produced between June 2020 and August 2020, are potentially affected.

Q2. What is the specific issue?

The tire pressure label may contain incorrect information regarding tire size. Therefore, it may not meet a Federal requirement.

Q3. Why are other models / vehicles not included in this Non-Compliance Recall?

Other models contain a tire pressure label containing the correct tire size.

Q4. Can I continue to drive my vehicle?

Yes. However, when you receive a letter from BMW advising you of this recall, you should make an appointment to have this important Non-Compliance Recall performed by an authorized BMW center as soon as possible. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

Q5. Can I determine if this issue exists in my vehicle?

No.

Q6. How did BMW become aware of the issue?

BMW became aware of the issue through our quality control procedures.

Q7. How will I be informed of this Non-Compliance Recall?

Letters will be mailed to owners in <u>October</u> via First Class mail advising them of this Non-Compliance Recall and requesting them to schedule an appointment with an authorized BMW center to have the remedy performed. Owners can locate their nearest authorized BMW center at <u>www.bmwusa.com/dealer</u>. To ensure BMW has the most recent contact and vehicle information, owners should register their vehicle at <u>www.bmwusa.com/myBMW</u>. Registration is free, and will give them access to factory initiated campaigns and other information specific to their BMW.

Q8. How will my vehicle be remedied?

The tire information label will be inspected and, if necessary, replaced for free and will take about one hour.

Q9. Do I have to wait for my letter to have my vehicle serviced?

No. Please contact an authorized BMW center to have this important Non-Compliance Recall performed. For the latest updates to this Non-Compliance Recall, please visit <u>www.bmwusa.com/recall</u>.