



**Your vehicle has a
safety recall!**

LICENSE PLATE
MAKE/MODEL
VIN

RECALL / RETIRO

Airbag May Not Deploy Properly or Airbag Inflator May Rupture (20TAD1)

DESCRIPTION / DESCRIPCIÓN

The subject vehicles are equipped with a front driver air bag with an inflator made by Takata. According to information provided by Takata, the airbag may not deploy properly. This could result in underinflation of the airbag or the chance of an inflator rupture that could result in metal fragments striking the driver or other occupants.

RISK / RIESGO

If underinflation or inflator rupture occurs, this could increase the risk of injury or death to vehicle occupants.

FIX / SOLUCIÓN

 Scan this QR code to find a local authorized dealer that will inspect and, if necessary, replace the front driver airbag inflator with a new one **FREE OF CHARGE OR CALL 800-331-4331.**

This program is sponsored by Toyota Motor North America and is powered by Carma Project.



Safety is our mission. Learn how this notice got to your car at carmaprotects.com.

Hablamos Español



**Su vehículo se ve
afectado por una
CAMPAÑA DE SEGURIDAD
URGENTE!**