



Your vehicle has a safety recall!

LICENSE PLATE
MAKE/MODEL
VIN

RECALL / RETIRO

Front Turn Signal Bulb Brightness (20TA12)

DESCRIPTION / DESCRIPCIÓN

In the subject vehicles, the wire harness connected to the front turn signal bulbs was assembled incorrectly, causing them not to illuminate as brightly as intended.

RISK / RIESGO

If oncoming traffic is unable to notice the front turn signals or front hazard warning lights, it may result in an increased risk of a crash.

FIX / SOLUCIÓN



Scan this QR code to find a local authorized dealer that will modify the wire harness connected to the front turn signal bulbs **FREE OF CHARGE** OR CALL 800-331-4331.

This program is sponsored by Toyota Motor North America and is powered by Carma Project.



U.S. Department of Transportation



Safety is our mission. Learn how this notice got to your car at carmaprotecta.com.

Hablamos Español



Su vehículo se ve afectado por una CAMPAÑA DE SEGURIDAD URGENTE!