



December, 2020

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2021 F-650 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **20S36 - Cabin Floor and Seat Mount Thermal Management Repairs**

What is the issue? On your vehicle, certain heat protection components for the cab may not have been installed, including an underbody heat shield, a thermal insulator patch under the floor mat, or covers for seat bolts and the seat pedestal.

This may result in elevated temperatures at locations on the interior cabin floor or seat attachments during high load and high ambient temperature driving conditions. There is a risk of injury if there is contact with exposed skin at these locations. There is a risk of skin irritation and/or a minor burn.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: www.owner.ford.com.

Thank you for your attention to this very important matter.

December de, 2020

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2021 F-650 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **20S36 - Reparaciones de la gestión térmica del soporte del asiento y pisode la cabina**

¿Cuál es el problema? Determinados componentes de protección contra calor de la cabina de su vehículo podrían no haberse instalado correctamente, incluido del protector contra calor de la parte inferior de la carrocería, el parche aislante térmico debajo del tapete del piso o las cubiertas de los tornillos del asiento y el pedestal del asiento.

Esto podría provocar un aumento considerable de las temperaturas de determinados aditamentos del piso o de los asientos en el interior de la cabina, cuando la temperatura ambiental es elevada y se maneja con mucha carga. Si toca alguno de estos sitios, corre el riesgo de sufrir alguna lesión en la piel, ya sea irritación o una quemadura menor.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: www.owner.ford.com.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

C / 0001 / 000000000000071 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

