



March, 2021

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Corsair has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: 20S41 - Rear coil spring inspection

What is the issue? On your vehicle, there may not be enough space between the rear coil spring and the rear toe link bracket.

Insufficient clearance may result in the spring contacting the toe link bracket causing wear to the protective coating of the spring. Over time, the risk of corrosion due to the removal of protective coating can reduce the full life of the spring and may cause spring fracture. If the spring fractures, it may separate from the vehicle and cause a potential road hazard, increasing the risk of a crash for other vehicles.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: owner.lincoln.com.

Thank you for your attention to this very important matter.

Marzo de, 2021

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2020 Corsair las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 20S41 - Inspección del resorte helicoidal trasero

¿Cuál es el problema? Es posible que en su vehículo no haya suficiente espacio entre el resorte helicoidal trasero y el soporte del tirante de ajuste de convergencia trasero.

Un espacio insuficiente podría generar un contacto del resorte con el soporte del tirante de ajuste de convergencia, lo cual podría provocar desgaste en el recubrimiento de protección del resorte. Con el tiempo, el riesgo de corrosión debido al retiro del recubrimiento de protección podría reducir la vida útil del resorte y podría fracturar el resorte. Si el resorte se fractura, podría separarse del vehículo y causar un potencial peligro en el camino, que aumenta el riesgo de impacto para otros vehículos.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: owner.lincoln.com.

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

A / 0101 / 000000000000026 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

