



March, 2021

\* \* \* IMPORTANT SAFETY RECALL REMINDER \* \* \*

According to our records, your 2020 Escape has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number    20S59 - Body control module replacement  
and Description:**

**What is the issue?** On your vehicle, it may be possible that the Body Control Module (BCM) intermittently may not pick up the signal from the rear Tire Pressure Monitoring System (TPMS) sensors or the Remote Key Fob.

This may result in an inadequate TPMS warning in the event of a low tire pressure condition, intermittent TPMS malfunction cluster warnings, or Remote Key Fobs that operate at a reduced distance from the vehicle. Low tire pressure may lead to poor vehicle handling and a possible loss of vehicle control, increasing the risk of crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [owner.ford.com](http://owner.ford.com).

Thank you for your attention to this very important matter.

Marzo de, 2021

\* \* \* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \* \* \*

SegUR nuestros registros, no se realizaron en sur 2020 Escape las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 20S59 - Reemplazo del módulo de control de la carrocería

**¿Cuál es el problema?** Es posible que el módulo de control de la carrocería (BCM) de su vehículo de forma intermitente no reciba la señal de los sensores traseros del sistema de monitoreo de la presión de las llantas (TPMS) o del llavero transmisor.

Esto se podría traducir en una advertencia no correspondiente del TPMS en caso de existir una condición de presión de llanta baja, advertencias intermitentes de mal funcionamiento del TPMS en el tablero o llaveros transmisores que funcionan a una distancia reducida del vehículo. Una baja presión de las llantas podría provocar una maniobrabilidad deficiente del vehículo y una posible pérdida de control, lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [owner.ford.com](http://owner.ford.com).

Gracias por su atención en este asunto sumamente importante.




P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▼ THEN FOLD, REMOVE THESE SIDE EDGES FIRST, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼

B / 0231 / 000000000000065 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▼ THEN FOLD, REMOVE THESE SIDE EDGES FIRST, CREASE AND TEAR THIS STUB ALONG PERFORATION ▼