

Toyota Motor North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Stop: W4-2D
6565 Headquarters Drive
Plano, TX 75024

June 4, 2020

AMENDED DEFECT INFORMATION REPORT (20V-033)

This supplements Toyota's Part 573 Report (20V-033) of January 22, 2020 concerning the front driver airbag inflator (Takata-designated NADI) issue on certain Toyota RAV4, RAV4 EV, Supra, and Celica vehicles.

The Description of Corrective Repair Action is revised as noted below:

Description of Corrective Repair Action:

When the remedy is available, all known owners of the affected Toyota vehicles will be notified by first class mail to return their vehicles to a Toyota dealer. Dealers will inspect the steering wheel type and, in some cases, the airbag and inflator serial numbers. If necessary, based on these inspections, dealers will replace the front driver airbag inflator with a newly designed one made by a supplier different from the original.