

Action Required: Model X Steering Bolt Recall

Tesla issued a recall to proactively retrofit a power steering component in certain Model X vehicles built before mid-October 2016. Our records indicate that your Model X vehicle 5YJ312345 may be affected and has not yet received a replacement of the steering component. Required parts are available.

Most vehicles will only need the steering bolts replaced, which takes about an hour. If your vehicle has broken bolts, or if any break during removal, we will also replace your steering gear, which takes approximately four-to-five hours.

To complete the repair, schedule a service appointment using the Tesla app by selecting 'Schedule Service' > 'Other' > 'Something else' and entering the note, 'Open Recall Repair - Steering Bolt.' There is no need for further action if you have already completed this repair. For more information related to this recall, please visit the [Recall Information Page](#).