

CAMPAIGN LAUNCH STATUS

H283 SAFETY RECALL 10MY XF-FUEL TANK OUTLET FLANGE CRACKING



SAFETY RECALL H283 – FUEL TANK OUTLET FLANGE

AFFECTED MODELS	10MY XF (X250) with 4.2L engines
NAS VOLUME AFFECTED	2907 USA 79 CAN
REPAIR	Affected vehicles will have the fuel tank outlet flange replaced with a component with revised design
REPAIR TIME	Est 0.8 hrs + DIDO
LAUNCH TARGET	May 29 th 2020
Notes	Interim customer mailing by 4/9/2020

- On affected vehicles retailer's have reported the fuel tank outlet flange is cracked. This can cause fuel odor, a check engine light and occasionally liquid fuel on the ground.
- Affected vehicles will be repaired with a new flange. Similar to J059 Recall for XF with 5.0L engines
- Retailer notification issued 2/27/20 in bulletin NAS20.02.022
- Parts are currently not available. Forecast date will be announced in the bulletin when known
- Customers must be advised by mail on or before April 9th 2020 even if a repair is not available at that time