

CAMPAIGN LAUNCH STATUS

H283 SAFETY RECALL 10MY XF - FUEL TANK OUTLET FLANGE CRACKING



SAFETY RECALL H283 – FUEL TANK OUTLET FLANGE	
AFFECTED MODELS	10MY XF (X250) with 4.2L engines
NAS VOLUME AFFECTED	2907 USA
REPAIR	Affected vehicles will have the fuel tank outlet flange replaced with a component with revised design
REPAIR TIME	Est 0.8 hrs + DIDO
LAUNCH	TBC
Notes	Interim customer mailing by 4/9/2020

H280 SERVICEACTION – BECM SOFTWARE	
AFFECTED MODELS	19-20MY I-PACE
NAS VOLUME AFFECTED	1611 USA*
REPAIR	Affected vehicles will have new software downloaded to the Battery Energy Control Module.
REPAIR TIME	0.2 + 0.2 DIDO
LAUNCHED	March 3rd 2020
Notes	*Approx. 360 units will be updated in ports

