

CAMPAIGN LAUNCH STATUS

N428 - SAFETY RECALL 17-18MY DISCOVERY - TRAILER LAMPS



SAFETY RECALL N428 – TRAILER STOP LAMP FUNCTIONALITY

AFFECTED MODELS	2017-2018MY DISCOVERY
VOLUME AFFECTED	1,553 USA 76 CAN All retailed
REPAIR	Affected vehicles require a software update to the Body control module (BCM)
REPAIR TIME	0.2 hrs + Drive in/out
REPAIR LAUNCHED	March 26 th 2020
Notes	Customer mailing by May 8 th 2020

- When vehicles with halogen headlamps have a trailer lighting board connected to the electrical trailer socket and the Daytime Running Lamps (DRL) are on, the trailer lamps will not operate unless a turn indicator is switched on.
- Where the trailer stop lamps fail to illuminate, other road users may not be aware that the vehicle may be slowing down or stopping, this will increase the risk of a crash
- Halogen headlamps were discontinued on Discovery at the end of 18MY.