CAMPAIGN LAUNCH STATUS

NEW RECALLS AND SERVICE ACTIONS





SERVICE ACTION N400 - BATTERY GROUND STUD		RECALL N459 – VEHICLE DOOR MAY NOT LATCH	
AFFECTED MODELS	19-20 MY DISCOVERY	AFFECTED MODELS	16MY RANGE ROVER AND RANGE ROVER SPORT
VOLUME AFFECTED	1789 USA 204 CAN	VOLUME AFFECTED	785 USA
REPAIR	The battery cable ground stud may be loose in the body and needs to be replaced. Insufficient ground contact may lead to intermittent operation of electrical equipment.	REPAIR	Certain vehicles previously included in N336 door latch recall may have not been fully repaired . This new recall will ensure the required process to check latch operation and update software is completed fully.
REPAIR TIME	0.2 hrs + Drive in/out	REPAIR TIME	Between 0.2 hrs. and 1.6 hrs. + Drive in/out
CAMPAIGN LAUNCH	July 1 st 2020	TARGET CAMPAIGN LAUNCH	July 7th 2020
Notes	Requires special stud tool and new studs supplied by Bosch	Notes	