

## CAMPAIGN LAUNCH STATUS

### NEW SAFETY RECALL N476- DOOR MAY NOT LATCH



#### RECALL N476 – VEHICLE DOOR MAY NOT LATCH

AFFECTED MODELS	13-16MY RANGE ROVER & 14-16MY RANGE ROVER SPORT
VEHICLE VOLUME AFFECTED	6,211 USA
REPAIR	Certain vehicles previously included in N335 door latch recall may have not been fully repaired. This new recall will ensure all steps in the required process to check latch operation and update software are completed fully. Initially software will be delivered via manual patch and each repair will require LTS support via a TA. Manual patch will be replaced by a standard SDD release
REPAIR TIME	Between 0.3 hrs. and 3.7 hrs, (depending on number of door latches needing modification) + Drive in/out
TARGET CAMPAIGN LAUNCH	Date of availability of special manual software patch is to be confirmed.
Notes	Notification Bulletin NAS20.07.009. issued July 10 <sup>th</sup> . N335 recall will also be republished with the same updated procedure and software.