

CAMPAIGN LAUNCH STATUS

NEW SAFETY RECALL N491 20-21MY RANGE ROVER SPORT



SAFETY COMPLIANCE RECALL N491 - INCORRECT TIRE PRESSURE & CERTIFICATION LABELS

AFFECTED MODELS	20-21MY Range Rover Sport with 19" wheels
VOLUME AFFECTED	1,087 USA 52 Canada
REPAIR	Labels affixed to affected vehicles contain incorrect tire pressure data. All vehicles will require replacement of the VIN certification label and the white Tire Placard both located at base of the driver's side B post. Replacement labels are to be ordered from the Mahwah special order team using the VINREQ form.
REPAIR TIME	0.2 hrs + drive in/out
CAMPAIGN LAUNCH	Target by October 23 rd 2020
Notes	Retailers have been notified by US bulletin NAS20.10.007 and Canadian bulletin NAS20.10.008 on October 8 th , 2020. Refer to BBSS for c 59 sold vehicles at retailers