

Action Required: Model X Steering Bolt and Roof Applique Recall

Our records indicate that your Model X vehicle 5YJ312345 may be affected by recent Steering Bolt and Roof Applique recall notices and has not yet received the required inspection or repairs. Required parts are currently available.

Your appointment will take a few hours to retrofit the bolts for the steering bolt recall and to inspect the roof applique. To complete the repairs, schedule a service appointment using the Tesla app by selecting 'Schedule Service' > 'Other' > 'Something else' and entering the note, 'Open Recall Repairs - Steering Bolt and Roof Applique.'

There is no need for further action if you have already completed both repairs. To confirm, please visit <https://www.tesla.com/vin-recall-search..>