

## Action Required: Model X Front and Spine Applique Recall

Tesla issued a recall to proactively inspect and repair front and spine applique in certain Model X vehicles built before August 2016. Our records indicate that your Model X vehicle 5YJ312345 may be affected and has not yet completed the inspection. The inspection will take less than five minutes. If necessary, a repair will take about an hour and a half.

To complete the inspection and repair, schedule a service appointment using the Tesla app by selecting 'Schedule Service' > 'Other' > 'Something else' and entering the note, 'Open Recall Repair—Roof Applique.'

There is no need for further action if you have already completed this repair. To confirm, please visit <https://www.tesla.com/vin-recall-search>.