

# CAMPAIGN LAUNCH STATUS

## RECALL UPDATE



### SAFETY RECALL N523 - L551 2<sup>nd</sup> ROW SEAT BELTS – INCORRECT SERVICE PART

AFFECTED MODELS	20MY Range Rover Evoque
VOLUME AFFECTED	13 USA
REPAIR	Affected vehicles have, during a previous service repair been fitted with 2 <sup>nd</sup> row seat belts that do not meet USA FMVSS standards. Seat belt part numbers are to be inspected and any non-NAS parts will be replaced.
REPAIR TIME	Est. between 0.2 and 0.8 hrs + Drive in/out
CAMPAIGN LAUNCH	Target: January 20 <sup>th</sup> , 2021
Notes	Retailer Notification January 7 <sup>th</sup> , 2021 by Aftersales Bulletin. One unsold unit

### SAFETY RECALL N524 - L551 FRONT SEAT COVER MATERIAL

AFFECTED MODELS	20MY Range Rover Evoque
VOLUME AFFECTED	66 USA
REPAIR	Affected vehicles have been built with front seat cover material that does not conform with FMVSS/CMVSS flammability safety standard. Seat covers will be replaced with conforming product.
REPAIR TIME	Est 0.8hrs+Drive in/out
CAMPAIGN LAUNCH	Target: February 15 <sup>th</sup> , 2021
Notes	Retailer Notification by Aftersales Bulletin is on January 7 <sup>th</sup> , 2021. Three units are unsold.

### SAFETY RECALL N516- L551 SPEEDOMETER UNITS DISPLAY

AFFECTED MODELS	2020 MY Range Rover Evoque
VOLUME AFFECTED	23 USA
REPAIR	A gateway module software update is required to correct errors with the instrument cluster speedometer Mph, Km/h display. New software is released to Pathfinder.
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	Target : 01/08/2021
Notes	Retailer notification and stop sale published Dec 17 <sup>th</sup> 2020. Bulletin NAS20.12.011. One unsold unit.