

## CAMPAIGN LAUNCH STATUS

### N516 RECALL - INCORRECT SPEEDOMETER UNITS DISPLAY



#### SAFETY RECALL N516- L551 SPEEDOMETER UNITS DISPLAY

AFFECTED MODELS	2020 MY Range Rover Evoque
VOLUME AFFECTED	23 USA 2 Canada
REPAIR	A gateway module software update is required to correct errors with the instrument cluster speedometer Mph, Km/h display. New software is released to Pathfinder.
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	01/07/2021
Notes	One unsold unit.



PRINTED COPIES ARE UNCONTROLLED