



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

April 22, 2021

Ms. Larissa Stoffels  
Exec Mgr, Vehicle Safety  
Daimler Trucks North America, LLC  
4747 N. Channel Ave  
Portland, OR 97217

NEF-107MR  
21E-029

**Subject:** Steering Arm and Tie Rod Bolts May Fracture

Dear Ms. Stoffels:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

DETROIT/MODEL 2/9999  
DETROIT/MODEL 3/9999

**Mfr's Report Date:** April 16, 2021

**NHTSA Campaign Number:** 21E-029

**Components:**

STEERING:CRITICAL FASTENERS  
STEERING:LINKAGES:TIE ROD ASSEMBLY

**Potential Number of Units Affected:** 172

**Problem Description:**

Daimler Trucks North America, LLC (DTNA) is recalling certain Detroit Model 2 and 3 axles. The steering arm and tie rod bolts may have a defective seam that can fracture.

**Consequence:**

A fractured bolt may cause a loss of steering, increasing the risk of a crash.

**Remedy:**

DTNA will notify owners, and dealers will replace the tie rod arm and steering arm bolts, free of charge. The recall is expected to begin June 10, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-884.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Daimler Trucks North America, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement