



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

January 27, 2021

Ms. Tara Underwood
Senior Manager, Technical Compliance
Nissan North America, Inc.
One Nissan Way
Franklin, TN 37027

NEF-150SS
21V-020

Subject: Brake Light Switch Relay may Stick

Dear Ms. Underwood:

This letter serves to acknowledge Nissan North America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NISSAN/PATHFINDER/2013-2015

Mfr's Report Date: January 20, 2021

NHTSA Campaign Number: 21V-020

Components:

EXTERIOR LIGHTING:BRAKE LIGHTS:SWITCH

Potential Number of Units Affected: 267,276

Problem Description:

Nissan North America, Inc. (Nissan) is recalling certain 2013-2015 Nissan Pathfinder vehicles. The location of the brake light switch may cause the brake light switch relay to repeatedly open and close. Overtime, this can cause the relay to stick in the "ON" position, with the brake lights remaining illuminated even when the brakes are not applied. Additionally, this may interfere with the brake-shift interlock, allowing the driver to shift the vehicle out of the "Park" position, without depressing the brake pedal.

Consequence:

Continual illumination of the brake lights can prevent other drivers from realizing the vehicle is actually slowing down, increasing the risk of a crash. With the brake override activated, the driver will not be able to accelerate normally, increasing the risk of a crash. The driver can shift the vehicle out of the "PARK" position without depressing the brake, allowing the vehicle to rollaway, increasing the risk of injury.

Remedy:

Nissan will notify owners, and dealers will inspect and, as necessary, swap positions with the Automatic Speed Control Device (ASCD) switch, or replace the brake light switch, free of charge. The recall is expected to begin March 1, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall PC786. Note: this recall supersedes 16V-380.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Shiver who may be reached by phone at (202) 366-7401, or by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,



Joshua Neff
Chief, Recall Management Division
Office of Defects Investigations
Enforcement