

U.S. Department of Transportation

National Highway Traffic Safety Administration

February 17, 2021

Ms. Helen Riehle Safety Integrity and Recall Manager BMW of North America, LLC 300 Chestnut Ridge Road Woodcliff Lake, NJ 07677 NEF-150DM

21V-062

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Possible Loss of Braking Assistance and ABS

Dear Ms. Riehle:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/740LI/2020-2021 BMW/745LE/2021 BMW/750LI/2020-2021 BMW/840I/2020-2021 BMW/M3/2021 BMW/M4/2021 BMW/M60LI/2020-2021 BMW/M8/2020-2021 BMW/M850I/2020-2021 BMW/X5/2019-2021 BMW/X6/2020-2021 BMW/X7/2019-2021

Mfr's Report Date: February 10, 2021

NHTSA Campaign Number: 21V-062

Components:

SERVICE BRAKES, HYDRAULIC:FOUNDATION COMPONENTS:MASTER CYLINDER SERVICE BRAKES, HYDRAULIC:POWER ASSIST:HYDRAULIC

Potential Number of Units Affected: 901

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2020-2021 8 Series Coupe, Grand Coupe and convertible 840i, 840i xDrive, M850i xDrive, M8 and 740 Li, 740 Li xDrive, 750 Li xDrive, M760 Li xDrive, X6 sDrive40i, X6 xDrive40i, X6 xdrive50i, X6 M50i, X6M, and 2019-2021 X5 sDrive40i, X5 xDrive40i, X5 xDrive50i, X5 M50i, X5M, X7 xDrive40i, X7 xDrive50i, X7 M50i, and 2021 M3, M3 Competition, M4 Coupe, M4 Competition Coupe, X5 xDrive45e, 745 Le xDrive. The rotor and shaft within the integrated brake system may not have been welded properly and could separate during a hard braking event, possibly resulting in a loss of the Antilock Brake System (ABS) and braking assistance.



Consequence:

A loss of ABS and a reduction in braking assistance can increase the risk of a crash.

Remedy:

BMW will notify owners, and dealers will replace the integrated brake system, free of charge. The recall is expected to begin April 5, 2021. Owners may contact BMW customer service at 1-800-525-7417.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigations

Enforcement

