



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

April 14, 2021

Mr. Jeff Chang
Honda (American Honda Motor Co.)
1919 Torrance Blvd
Torrance, CA 90501

NEF-107JK
21V-249

Subject: Rear Cushion Connecting Plate(s) May Break

Dear Mr. Chang:

This letter serves to acknowledge Honda (American Honda Motor Co.)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HONDA/CBR1000RR/2021

Mfr's Report Date: April 8, 2021

NHTSA Campaign Number: 21V-249

Components:

STRUCTURE

Potential Number of Units Affected: 89

Problem Description:

Honda (American Honda Motor Co.) is recalling certain 2021 CBR1000RR-R Fireblade SP motorcycles. The rear cushion connecting plate(s) may have been installed incorrectly, which may cause the plate(s) to break.

Consequence:

Broken plate(s) may cause a sudden drop to the vehicle height, increasing the risk of a crash or injury.

Remedy:

Honda will notify owners, and dealers will inspect and, as necessary, replace both rear cushion connecting plates free of charge. The recall is expected to begin June 7, 2021. Owners may contact Honda customer service at 1-866-784-1870. Honda's number for this recall is KL9.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Honda (American Honda Motor Co.)'s contact for this recall will be Jennifer Kruger who may be reached by email at jennifer.kruger@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement