



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 21, 2021

Mr. Kerry Legg
Vehicle Safety and Regulatory Compliance Manager
New Flyer of America, Inc.
711 Kernaghan Avenue
Winnipeg, MB
Canada R2C 3T4

NEF-107MR
21V-365

Subject: High Pressure Fuel Rail Assembly May Leak Fuel

Dear Mr. Legg:

This letter serves to acknowledge New Flyer of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NEW FLYER/XD35/2017-2021
NEW FLYER/XD40/2017-2021
NEW FLYER/XD60/2016-2021
NEW FLYER/XDE35/2017
NEW FLYER/XDE40/2016-2020
NEW FLYER/XDE60/2016-2020

Mfr's Report Date: May 18, 2021

NHTSA Campaign Number: 21V-365

Components:

FUEL SYSTEM, DIESEL:FUEL INJECTION SYSTEM:FUEL RAIL

Potential Number of Units Affected: 3,600

Problem Description:

New Flyer of America, Inc. (New Flyer) is recalling certain 2017-2021 XD40, XD35, 2016-2021 XD60, 2017 XDE35, 2016-2020 XDE40, XDE60 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak.

Consequence:

A fuel leak in the presence of an ignition source increases the risk of a fire.

Remedy:

New Flyer will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters are expected to be mailed May 31, 2021. Owners may contact New Flyer customer service at 1-204-224-6706. New Flyer's number for this recall is R21-008.



Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received New Flyer's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

New Flyer of America, Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement