

October 21, 2021

Mr. Adrian Diaz Assistant Engineering Director Automotive Safety Office Ford Motor Company 330 Town Center Drive Suite 500/5024 Dearborn, MI 48126

Subject: Inadequate Bonding on Moonroof Glass Panel

Dear Mr. Diaz:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: FORD/BRONCO SPORT/2021

Mfr's Report Date: October 15, 2021

NHTSA Campaign Number: 21V-809

Components: VISIBILITY:SUN/MOON ROOF ASSEMBLY

Potential Number of Units Affected: 1,036

Problem Description:

Ford Motor Company (Ford) is recalling certain 2021 Bronco Sport vehicles. The moonroof glass may not have been bonded correctly to the moonroof frame, which could result in the glass panel detaching from the vehicle.

Consequence:

A detached glass panel can become a road hazard, and increase the risk of a crash or injury.

Remedy:

Dealers will inspect the moonroof glass date code and replace the glass, if necessary, free of charge. Owner notification letters are expected to be mailed November 29, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S46.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

HTSA

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107DM 21V-809

Please ensure the following requirements are met:

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Ford Motor Company's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Lee And

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

