

Part 573 Safety Recall Report

21E-059

Manufacturer Name : Shenzhenshi Axi Technology Co. LTD**Submission Date :** JUL 08, 2021**NHTSA Recall No. :** 21E-059**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Shenzhenshi Axi Technology Co. LTD

Number of potentially involved : 1,143

Address : Dezhong Gongyeyuan 5 Building 310 R
7 Wuheshequ Lipu Rd, Longgang
District shenzhen 00 518000

Estimated percentage with defect : 100 %

Company phone : 18098949735

Equipment Information :

Brand / Trade 1 : OXILAM

Model : F3-H11

Part No. : led headlight bulb

Size : NR

Function : NR

Descriptive Information : Shenzhenshi Axi Technology Co., LTD is recalling certain aftermarket OXILAM headlight bulbs, F3-H11 and F3-9005 models sold through Amazon.com. These bulbs may create excessive glare or brightness for oncoming traffic. As such, these bulbs failed to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Related(sold) quantity:

F3-H11:954 sets

F3-9005: 189 sets

Production Dates : NOV 01, 2019 - MAR 10, 2021

Description of Noncompliance :

Description of the Noncompliance : The led headlight bulbs' design and brightness do not comply with the FMVSS108 requirement

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The high brightness can increase the risk of a crash for oncoming drivers**Description of the Cause :** NR**Identification of Any Warning that can Occur :** NR

Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : Zhongshan YishidaGuangdian Tech Co., Ltd

Address : No.16 Gongye road, first industrial zone
Tanzhou Zhen Zhongshan Foreign States

Country : China

Chronology :

On or about Feb 09, 2021, NHTSA informed Shenzhenshi Axi Technology Co., Ltd that, based the test results obtained by NHTSA of the led headlight bulbs (F3-H11), certain deficiencies were noted which constituted possible noncompliances with FMVSS No. 108. After we were notified of violations, we have stopped selling the products and have been actively cooperating with NHTSA's investigation and provide the information and sales data required by NHTSA.

Description of Remedy :

Description of Remedy Program : We offer replacements, free of charge, each led bulb customer purchased in the United Sates with a halogen bulb that complies with the requirements of FMVSS 108.

How Remedy Component Differs from Recalled Component : The replacement bulb is halogen headlight bulbs which comply with the requirements of FMVSS 108.

Identify How/When Recall Condition was Corrected in Production : Please write an email to service@oxilam.com to get a replacement bulb. You will need to provide an original order number, receipt or other proof of purchase in the email. The remedy is available immediately after the recall posted.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUL 12, 2021 - AUG 31, 2021

Planned Owner Notification Date : JUL 12, 2021 - AUG 31, 2021

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported