

# Part 573 Safety Recall Report

## 21E-062

**Manufacturer Name :** Shenzhen Dianliangzhihui Tech Co.

**Submission Date :** JUL 07, 2021

**NHTSA Recall No. :** 21E-062

**Manufacturer Recall No. :** NR



### Manufacturer Information :

### Population :

**Manufacturer Name :** Shenzhen Dianliangzhihui Tech Co.

**Number of potentially involved :** 4,357

**Address :** 98 Baonongbeixiang, Baohedasha B Bu  
Shenzhen 00 518100

**Estimated percentage with defect :** 100 %

**Company phone :** 19527558343

### Equipment Information :

**Brand / Trade 1 :** LASFIT

**Model :** A30-LAplusH11-NFBA

**Part No. :** A30-LAplusH11-NFBA

**Size :** A30-LAplusH11-NFBA

**Function :** EXTERIOR LIGHT

**Descriptive Information :** Components: EXTERIOR LIGHTING: HEADLIGHTS bulb  
Potential Number of Units Affected: 4357

**Production Dates :** OCT 01, 2020 - MAY 01, 2021

### Description of Defect :

**Description of the Defect :** DianLiangzhihuiTechnology Co., Ltd. is recalling certain aftermarket headlight bulbs, in configurations A30-LAplusH11-NFBA only sold through Amazon.com. Those replaceable light source's maximum luminous flux was above the maximum limit during the first ten minutes, then falls within legal limits; there are dimensional requirements that were not met in that there are no resistive filaments, and does not comply with marking requirements.

**FMVSS 1 :** 108 - Lamps, reflective devices, and assoc. Equipment

**FMVSS 2 :** NR

**Description of the Safety Risk :** The maximum luminous flux was above the maximum limit, and may cause excessive brightness for the first ten minutes of use. At this time, there are no known instances of crashes or injuries caused by excessive brightness by use of this bulb

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Involved Components :**

Component Name : EXTERIOR LIGHT

Component Description : Headlight Bulbs

Component Part Number : A30-LAplusH11-NFBA

**Supplier Identification :****Component Manufacturer**

Name : Guangzhou jiujiayi dianzi Tech CO.

Address : guangzhoushi baiyunqu renhezhen gonghuag  
guangzhou Foreign States 510470

Country : China

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : DianLiangzhihuiTechnology Co., Ltd will notify customers to change back to halogen, instructing them to return the bulbs for a full refund, To qualify for such replacement, a claimant must fill out a recall request form and provide proof of purchase, and agree to return the recalled bulb. The recall is expected to begin August 1st 2021, customer can contact customer service email : recall2021dl@163.com

How Remedy Component Differs from Recalled Component : A30-LAplusH11-NFBA

Identify How/When Recall Condition was Corrected in Production : Unknown. we are not the manufacturer. The manufacturer was contacted and made aware of the issue.

**Recall Schedule :**

Description of Recall Schedule : we don't have dealers or distributors.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported