

Part 573 Safety Recall Report

21V-088

Manufacturer Name : Newmar Corporation**Submission Date :** FEB 18, 2021**NHTSA Recall No. :** 21V-088**Manufacturer Recall No. :** 21V 041**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 253

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2022 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan Chassis, The steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

Dutch Star=140

Production Dates : JAN 07, 2020 - FEB 09, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2020-2022 Newmar King Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan Chassis, The steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

King Aire= 17

Production Dates : JAN 07, 2020 - FEB 09, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2020-2022 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan Chassis, The steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.
Essex=19

Production Dates : JAN 07, 2020 - FEB 09, 2021

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2020-2022 Newmar London Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan Chassis, The steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.
London Aire=39

Production Dates : JAN 07, 2020 - FEB 09, 2021

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2020-2022 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan Chassis, The steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.
Mountain Aire=38

Production Dates : JAN 07, 2020 - FEB 09, 2021

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes built on a Spartan Chassis, The steering gear mounting fasteners may come loose and fall out or interfere with other steering components. If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the steering gear mounting fasteners interfere with other steering components, such as a pitman arm, it may cause difficulty in steering or pin the steering wheel to one direction, which could increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On 2/11/2021, Shyft Group Inc. sent notice of a defect on Spartan Chassis. Today, 02/18/2021, Newmar is giving notice to NHTSA.

Description of Remedy :

Description of Remedy Program : Shyft Group Inc. will be conducting this recall in its entirety. Owners will be directed to the appropriate service provider for repair. The steering gear mounting fasteners will be removed and replaced. New fasteners will be installed using loctite and a washer then tightened to specification. This will be done at no charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : On or before 4/19/2021, customer/dealer letters will be mailed out.

Planned Dealer Notification Date : APR 19, 2021 - APR 19, 2021

Planned Owner Notification Date : APR 19, 2021 - APR 19, 2021

* NR - Not Reported