

Part 573 Safety Recall Report

21V-248

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** APR 08, 2021**NHTSA Recall No. :** 21V-248**Manufacturer Recall No. :** H349**Manufacturer Information :****Population :****Manufacturer Name :** Jaguar Land Rover North America, LLC**Number of potentially involved :** 3**Address :** 100 Jaguar Land Rover Way**Estimated percentage with defect :** 100 %**Mahwah NJ 07495****Company phone :** 8188500**Vehicle Information :****Vehicle 1 :** 2018-2018 JAGUAR XE**Vehicle Type :** LIGHT VEHICLES**Body Style :** 4-DOOR**Power Train :** NR

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving One 2017MY Jaguar XE vehicle, One 2018MY Jaguar XE vehicle and One 2020MY Jaguar XE vehicle in the US, built at the Castle Bromwich and Solihull UK Vehicle Assembly Plants, on January 06, 2017 September 14, 2017 and December 11, 2019. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for affected vehicles is determined by specific model type and specification, 2017MY to 2020MY Jaguar XE vehicles, which have received an in-service replacement rear rail service assembly.

Production Dates : SEP 14, 2017 - SEP 14, 2017**VIN Range 1 : Begin :****End :** Not sequential**Vehicle 2 :** 2017-2017 JAGUAR XE**Vehicle Type :** LIGHT VEHICLES**Body Style :** 4-DOOR**Power Train :** NR

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving One 2017MY Jaguar XE vehicle, One 2018MY Jaguar XE vehicle and One 2020MY Jaguar XE vehicle in the US, built at the Castle Bromwich and Solihull UK Vehicle Assembly Plants, on January 06, 2017 September 14, 2017 and December 11, 2019. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for affected vehicles is determined by specific model type and specification, 2017MY to 2020MY Jaguar XE vehicles, which have received an in-service replacement rear rail service assembly.

Production Dates : JAN 06, 2017 - JAN 06, 2017**VIN Range 1 : Begin :****End :** Not sequential

Vehicle 3 : 2020-2020 JAGUAR XE

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : NR

Descriptive Information : Jaguar Land Rover is conducting a voluntary safety recall campaign involving One 2017MY Jaguar XE vehicle, One 2018MY Jaguar XE vehicle and One 2020MY Jaguar XE vehicle in the US, built at the Castle Bromwich and Solihull UK Vehicle Assembly Plants, on January 06, 2017 September 14, 2017 and December 11, 2019. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for affected vehicles is determined by specific model type and specification, 2017MY to 2020MY Jaguar XE vehicles, which have received an in-service replacement rear rail service assembly.

Production Dates : DEC 11, 2019 - DEC 11, 2019

VIN Range 1 : Begin :

End :

Not sequential

Description of Defect :

Description of the Defect : A concern has been identified on 3 Jaguar XE vehicles where, one or both, of the rear rail assembly (rear longitudinal armatures) installed as part of an aftermarket repair, may not have the specified structural strength due to a number of spot welds being missed during service part manufacture.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Vehicles in this condition are at risk of the rear bumper beam detaching during vehicle recovery or, in a situation where the vehicle is towing a trailer, the tow-bar assembly could detach and control of the trailer will be lost. This could increase the risk of a vehicle crash and personal injury to people in the surrounding area.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Reinforcement Panel Righthand

Component Description : Reinforcement Panel Righthand

Component Part Number : T2H4167

Component Name 2 : Reinforcement Panel Lefthand

Component Description : Reinforcement Panel Lefthand

Component Part Number : T2H4168

Component Name 3 : Extension Panel Righthand

Component Description : Extension Panel Righthand

Component Part Number : T4N31664

Component Name 4 : Extension Panel Lefthand

Component Description : Extension Panel Lefthand

Component Part Number : T4N31665

Supplier Identification :

Component Manufacturer

Name : Jaguar Land Rover Limited

Address : Abbey Road

Whitley, Coventry Foreign States CV3 4LF

Country : United Kingdom

Chronology :

See File "Recall H349 Chronology".

Description of Remedy :

Description of Remedy Program : Retailers will correct the affected vehicles with replacement parts installed in line with aftermarket welding standards.

There will be no charge to owners for this repair.

Most affected vehicles will be covered under Jaguar's new vehicle warranty program. Therefore, reimbursement for pre-notice remedies are not necessary because the affected vehicles are still under warranty.

For vehicles outside of Jaguar's new vehicle warranty program, owners who have paid for a repair of this defect will be covered by the Jaguar Land Rover reimbursement plan, subject to the usual terms and conditions.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before May 28, 2021. Notifications to retailers will occur on April 22, 2021.

Planned Dealer Notification Date : APR 22, 2021 - APR 22, 2021

Planned Owner Notification Date : MAY 28, 2021 - MAY 28, 2021

* NR - Not Reported