

Part 573 Safety Recall Report

21V-503

Manufacturer Name : Maintainer Corporation of Iowa, Inc.

Submission Date : JUL 01, 2021

NHTSA Recall No. : 21V-503

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Maintainer Corporation of Iowa, Inc.

Number of potentially involved : 1

Address : 1701 2nd Ave.

Estimated percentage with defect : 100 %

Sheldon IA 51201

Company phone : 712-324-8125

Vehicle Alterer Information :

Vehicle 1 : 2015-2015 Maintainer Custom Bodies Heavy Rescues

Descriptive Information : The recall population was determined through a search of our purchasing records and verification from Code3, our supplier of the lamp, that we have only purchased 2 of the 79STTRBZ lamps with a purchase date in March of 2015. The ECCO recall was specific to model 79STTRBZ. These 2 affected lamps were installed on a single Maintainer Heavy Rescue therefore we have a single Heavy Rescue affected by this recall.

Production Dates : APR 03, 2015 - APR 03, 2015

Description of Defect :

Description of the Defect : Per ECCO Holdings Corp. Part 573 Safety Recall Report 20E-041. The subject lamps exceed the maximum permissible candela levels specified in Federal Motor Vehicle Safety Standard (FMVSS) No. 108 at certain test points.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Per ECCO Holdings Corp. Part 573 Safety Recall Report 20E-041. The increased photometric intensity does not comply with the requirements of FMVSS 108 and may adversely affect the vision of following drivers, increasing the risk of a vehicle crash without warning.

Description of the Cause : Per ECCO Holdings Corp. Part 573 Safety Recall Report 20E-041. The lamps do not meet the requirements of the relevant standard.

Identification of Any Warning that can Occur : N/A

Involved Components :

Component Name : Code 3

Component Description : 7x9 Stop-Tail-Turn-Reverse All-in-One LED Lamp

Component Part Number : 79STTRBZ

Supplier Identification :

Component Manufacturer

Name : ECCO Holdings Corporation

Address : 833 West Diamond
Boise Idaho 83705

Country : United States

Chronology :

Maintainer Corp received an email from NHTSA on 6/25/21 stating that ECCO Holdings corporation listed Maintainer as a purchaser of code3 79STTRBZ lamps involved in a safety recall. With the assistance of our supplier, Code3, it was determined that we had purchased a total of two 79STTRBZ lamps in 2015. We then linked those 2 lamps to a single Heavy Rescue assembled in our facility.
Refer to Safety Recall Report 20E-041

Description of Remedy :

Description of Remedy Program : Refer to Safety Recall Report 20E-041
Maintainer Corp will issue an owner notification letter to our single customer. This customer will be instructed to contact Code 3 to obtain a filter kit (Part No. CZ0199) free of charge.

How Remedy Component Differs from Recalled Component : Refer to Safety Recall Report 20E-041

Identify How/When Recall Condition was Corrected in Production : Refer to Safety Recall Report 20E-041

Recall Schedule :

Description of Recall Schedule : Maintainer has notified the customer via phone and will send the owner notification letter.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUL 06, 2021 - JUL 16, 2021

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported