3

Part 573 Safety Recall Report

Manufacturer Name :Eldorado National- California, Inc.Submission Date :OCT 06, 2023NHTSA Recall No. :21V-694Manufacturer Recall No. :NR



Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

21V-694

Manufacturer Information :

Manufacturer Name :Eldorado National- California, Inc.Address :9670 GALENA STREETRIVERSIDE CA 92509809-591-9557

Vehicle Information :

Vehicle 1:	2019-2021 ELDORADO NATIONAL EZRM
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES
Body Style :	OTHER
Power Train :	DIESEL
Descriptive Information :	Cummins, Inc. provided ElDorado National (ENC) with a spreadsheet of all the ENGINE SERIAL NUMBERS belonging to ENC. ENC then extracted those SERIAL NUMBERS from its data base providing the list of all buses with those SERIAL NUMBERS (Engines); detailing which customers will be notified of the defect.
Production Dates :	MAR 27, 2019 - JUN 15, 2021
VIN Range 1:	Begin : NR End : NR

Description of Defect :

Description of the Defect :	Cummins, Inc. (Cummins) is recalling certain L9 Diesel Engines, with part number D563027BX03, that are equipped with a remote Stage 2 fuel filter and pressurized hoses. A fuel leak may occur from the fuel hose between the fuel pump and remote fuel filter head.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A fuel leak in the presence of an ignition source increases the risk of a fire.
Description of the Cause :	The cause of the issue is inadequate design and quality of the fuel hose assembly.
	Persons operating in or around the vehicle may see smoke before sufficient heat creates a fire.

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

21V-694

Component Name 1 : CUMMINS INC.

Component Description : ENGINE MODEL L9 - DIESEL

Component Part Number : D563027BX03

Supplier Identification :

Component Manufacturer

Name :Cummins, IncAddress :BOX 3005MAIL CODE 41303 COLUMBUS Indiana 47202-3005Country :United States

Chronology:

On JULY 20, 2021, ELDORADO NATIONAL CALIFORNIA, INC. received communication from Cummins that one engine in the Recall 21E-063 for their Cummins L9 Remote Filter Hose Campaign had been shipped to ENC. ENC proceeded to identify which vehicle had received the engine and check warranty and service records for the unit.

On AUGUST 10, 2021, ELDORADO NATIONAL CALIFORNIA, INC. received communication from Cummins that an additional two (2) engines have been identified for the Recall 21E-063 for their Cummins L9 Remote Filter Hose Campaign and shipped to ENC. ENC proceeded to identify which vehicle had received the engine and check warranty and service records for the unit.

On August 27, 2021 ENC staff proposed to file a pass-through 573 notification and requested approval from REV Group.

Description of Remedy :

Description of Remedy Program :	The remedy will be to replace the subject fuel hoses, to and from the remote fuel filter, with fuel hoses of a new design. Cummins will cover the full "BURDEN of COST" for this campaign.
How Remedy Component Differs from Recalled Component :	The new fuel hoses will have a unique part number and are visibly different.

fart 575 Salety Ke	call Report	21V-694	Page 3
Identify How/When Recall Condition was Corrected in Production :		s with the new design fuel hoses beg National Vehicles are affected by th	
Recall Schedule :			
	49 CFR Part 577, performing the reports to NHTSA / Identify and condition was corrected in proc owner notification by September	l, including notifying owners pursua e remedy, and submitting quarterly l describe how and when the recall luction. ENC expects to begin deale er	status

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573