The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :Carson Trailer, Inc.Submission Date :NOV 24, 2021NHTSA Recall No. :21V-747Manufacturer Recall No. :Recall3

Manufacturer Information :

Manufacturer Name : Carson Trailer, Inc. Address : 14831 S. Maple Ave Gardena CA 90248

Company phone: 999

Vehicle Information :

Vehicle 1 :2021-2021 CARSON CARRIERSVehicle Type :TRAILERSBody Style :Power Train :NRDescriptive Information :there is a possibility that the spindle nuts in the trailer axles were insufficiently
torqued.Production Dates :MAY 25, 2021 - JUL 15, 2021VIN Range 1 : Begin :4hxbu1622nc223061End :4hxbu1628nc223890Not sequential

Description of Defect :

Description of the Defect :a certain number of spindle nuts were not torqued to prescribed standardsFMVSS 1 :NRFMVSS 2 :NRDescription of the Safety Risk :axle, tire or wheel failure may affect vehicle stability. this could a crash
improper torqueing of spindle nutIdentification of Any Warning
that can Occur :NR


Involved Components :

RATIONAL HIGHWAY TRAF SAFETY ADMINISTRATION

21V-747

Population :

Number of potentially involved : 870 Estimated percentage with defect : 100 %



Part 573 Safety Recall Report

Component Name 1 : Spindle Nut	
Component Description : Spindle Nut retains the hub assembly in the spindle	
Component Part Number : NR	
Supplier Identification :	
Component Manufacturer	
Name : Terran Axle	
Address : 1 Westbrook Corporate Center	
Westchester Illinois 60154	
Country : United States	
Terran management made a formal determination that remedial field action was necessary.	
Description of Remedy :	
Description of Remedy Program : For axles that have been in operation on a moving trailer and experience vibration.	
How Remedy Component Differs Remedy involves torqueing the spindle nut to prescribed standards from Recalled Component :	
Identify How/When Recall ConditionInspect each trailer axle and if spindle nut was insufficiently torqued, the was Corrected in Production :spindle nut was torqued to prescribed standards.	
Recall Schedule :	
Description of Recall Schedule : no dealer we are doing the repair.	
Planned Dealer Notification Date : SEP 30, 2021 - NOV 12, 2021	
Planned Owner Notification Date : NOV 12, 2021 - NOV 12, 2021	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573