OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 21V-747

**Manufacturer Name:** Carson Trailer, Inc.

Submission Date: DEC 03, 2021 NHTSA Recall No.: 21V-747 Manufacturer Recall No.: Recall3



### **Manufacturer Information:**

Manufacturer Name: Carson Trailer, Inc.

Address: 14831 S. Maple Ave

Gardena CA 90248

Company phone: 999

## **Population:**

Number of potentially involved : 870Estimated percentage with defect : 100 %

### **Vehicle Information:**

Vehicle 1: 2021-2021 CARSON CARRIERS

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: there is a possibility that the spindle nuts in the trailer axles were insufficiently

torqued.

Production Dates: MAY 25, 2021 - JUL 15, 2021

VIN Range 1: Begin: 4hxbu1622nc223061 End: 4hxbu1628nc223890 Not sequential

### **Description of Defect:**

Description of the Defect: a certain number of spindle nuts were not torqued to prescribed standards

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: axle, tire or wheel failure may affect vehicle stability or increase the risk of a

crash.

Description of the Cause: improper torqueing of spindle nut

Identification of Any Warning NR

that can Occur:

## **Involved Components:**

# Part 573 Safety Recall Report

21V-747

Page 2

Component Name 1: Spindle Nut

Component Description: Spindle Nut retains the hub assembly in the spindle

Component Part Number: NR

### **Supplier Identification:**

### **Component Manufacturer**

Name: Terran Axle

Address: 1 Westbrook Corporate Center

Westchester Illinois 60154

**Country: United States** 

### **Chronology:**

Terran management made a formal determination that remedial field action was necessary. Carson has nothing to report.

### **Description of Remedy:**

Description of Remedy Program : For axles that have been in operation on a moving trailer and experience

vibration.

How Remedy Component Differs Remedy involves torqueing the spindle nut to prescribed standards

from Recalled Component:

Identify How/When Recall Condition Inspect each trailer axle and if spindle nut was insufficiently torqued, the

was Corrected in Production: spindle nut was torqued to prescribed standards.

### **Recall Schedule:**

Description of Recall Schedule: no dealer we are doing the repairs.

Planned Dealer Notification Date : SEP 30, 2021 - NOV 12, 2021 Planned Owner Notification Date : NOV 12, 2021 - NOV 30, 2021

\* NR - Not Reported