The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :Provan Industries, LLCSubmission Date :JAN 03, 2022NHTSA Recall No. :21V-803Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Provan Industries, LLC Address : 4837 Edmund Hwy. West Columbia SC 29170 Company phone : 803-955-3001

Vehicle Information :

Vehicle 1:	2019-2020 Tiger Adventu	re Vehicle Bengal TX	
Vehicle Type :	LOW VOLUME VEHICLES		
Body Style :			
Power Train :	NR		
Descriptive Information :	Our records show that this recall potentially affects 13 Bengal campers produced between 09/19 and 01/21 with OPIM numbers 1310B- 1322B.		
Production Dates :	SEP 01, 2019 - JAN 01, 202	1	
VIN Range 1:	Begin : NR	End: NR	□ Not sequential

Population :

Description of Defect :

Lippert Components has determined that some window vents may experience an issue with the window adhesive bonding.
NR
NR
Inner and outer glass panes may become separated. A pane falling off may cause a crash or injury.
NR
None

Involved Components :

21V-803



Number of potentially involved :

Estimated percentage with defect : 50 %

13

Part 573 Safety Recall Report

21V-803

()	D O
.5	Page 2

Component Name 1:	Window vent	
	Galley window front vent	
Component Part Number :	6402-40-P SVD 54.7 X 081 G20 TP BK 4.000 RADII	
Component Name 2:	Window vent	
Component Description :	Galley window rear vent	
Component Part Number :	6402-40-R SVD 54.7 X 081 BK TP G20 4.000 RADII*	
Component Name 3 :	Window vent	
•	Couch window front vent	
	6402-40-R SVD 58.7 X 081 G20 TP BK 4.000 RADII	
Component Name 4 :	Window vent	
	Couch window rear vent	
component Description :		

Supplier Identification :

Component Manufacturer

Name :Lippert ComponentsAddress :88704 Expedite Way.
Chicago Illinois 60695Country :United States

Chronology :

None

The information contained in this report was submitted pursuant to 49 CFR §573

Page 3

Description of Remedy :

Description of Remedy Program :	Provan RV Industries will send an inspection gauge along with recall instructions to the potentially affected Bengal owners. Lippert Components will pay 0.4 hours labor to inspect the involved windows and/or 0.5 hours labor to replace any needed vent. Provan RV Industries will pay the repair shop directly and be reimbursed by Lippert Components later. Replacement parts are readily available.
How Remedy Component Differs from Recalled Component :	
Identify How/When Recall Condition was Corrected in Production :	NR
Recall Schedule ·	

Recall Schedule :

Description of Recall Schedule :No dealers or distributors.Planned Dealer Notification Date :NR- NRPlanned Owner Notification Date :NR- NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573