

Part 573 Safety Recall Report

21V-857

Manufacturer Name : Tracker Marine, LLC

Submission Date : NOV 04, 2021

NHTSA Recall No. : 21V-857

Manufacturer Recall No. : RT-0001



Manufacturer Information :

Manufacturer Name : Tracker Marine, LLC

Address : 2500 E. Kearney
Springfield MO 65898

Company phone : 417-873-4555

Population :

Number of potentially involved : 380

Estimated percentage with defect : 10 %

Vehicle Information :

Vehicle 1 : 2022-2022 Ranger Trail T22RT178 ,T22RT178B ,T22RT188 ,T22RT188B ,
T22RT188P ,T22RT188PB ,T22RT198P ,T22RT198PB ,T22VS1665 ,T22VS1682 ,
T22VS1782 ,T22VS1782B

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Basis was determined by date of manufacture minus trailers we still had at the plant that could be inspected/corrected prior to shipment. There are a total of 380 potential units affected.

Production Dates : JUN 30, 2021 - OCT 27, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Fenders may be improperly spaced which can cause tires to rub fenders.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Could cause premature wear on tires risking a blowout while underway.

Description of the Cause : Fenders improperly spaced causing tires to rub while trailer loaded.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

We had a customer report a rubbing tire which prompted further review on 11-1-2021. After further review, an additional stock trailer was found to have the same condition. We have opted to recall the trailers due to safety concerns.

Description of Remedy :

Description of Remedy Program : All potentially affected units will be checked to make sure there is 3/4 inch spacing from trailer frame. Customers will be instructed to take their trailer to any of our dealers for inspection/correction at no charge to the customer.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : Upon discovery of the concern, steps were added to manufacturing to make sure proper spacing on fenders.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 12, 2021 - NOV 15, 2021

Planned Owner Notification Date : NOV 12, 2021 - NOV 15, 2021

* NR - Not Reported