OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

21V-896

Manufacturer Name: Daimler Trucks North America, LLC

NHTSA Recall No.: 21V-896

Manufacturer Recall No.: FL-908



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America, LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 270 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2011-2022 Freightliner Business Class M2, SD 108, SD 114

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: All vehicles listed in DTNA's database as having been built with the particular tire and

rim combinations

Production Dates: OCT 15, 2010 - SEP 02, 2021

VIN Range 1 : Begin : NR End : NR

Vehicle 2: 2011-2022 Western Star 4700, 4900, 6900, 49X

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: All vehicles listed in DTNA's database as having been built with the particular tire and

rim combinations

Production Dates: OCT 15, 2010 - SEP 02, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Noncompliance:

Description of the On the affected vehicles, the tire/rim combination was not on the approved list

Noncompliance: from the Tire and Rim Association or listed as approved by the tire

manufacturer at the time of sale, as required by FMVSS 120, after the tire/rim

combination was removed from the list.

FMVSS 1: 120 - Wheels and rims- other than passenger cars

FMVSS 2: NR

Description of the Safety Risk: Failure to meet the standard without getting tire manufacturer approval

increases the risk of an accident.

Description of the Cause: NR Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: Certain tire/rim combinations

Component Description: NR Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

On Sep 29, 2021 DTNA was made aware of a potential tire rim mismatch. DTNA promptly began an investigation, in which it was found that the Tire and Rim Association had made changes to the approved wheel list for certain tires, removing certain combinations. Upon determining the existence of a noncompliance, on Nov 10, 2021 DTNA decided to conduct a non-compliance recall.

Description of Remedy:

Description of Remedy Program: The remedy has not been finalized. Repairs will be made by Daimler Trucks North America authorized service facilities.

> Details of the reimbursement plan will be included in the owner's notification letter.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Planned Dealer Notification Date : JAN 15, 2022 - JAN 15, 2022 Planned Owner Notification Date : JAN 15, 2022 - JAN 15, 2022

* NR - Not Reported