#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 21V-916

**Manufacturer Name:** Vermeer Manufacturing Company

NHTSA Recall No.: 21V-916

Manufacturer Recall No.: VMV0015



#### **Manufacturer Information:**

Manufacturer Name: Vermeer Manufacturing Company

Address: 1210 VERMEER ROAD EAST

PO BOX 200 PELLA IA 50219-0200

Company phone: 641-628-3141

# **Population:**

Number of potentially involved : 1,054 Estimated percentage with defect : 40%

#### **Vehicle Information:**

Vehicle 1: 2018-2021 Vermeer VX30

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Using various manufacturing documents, research was conducted to determine the

population of vacuum excavators affected by incorrect lug nut torque value listed in the operator's and maintenance manual. This incorrect lug nut torque value listed in

the operator's and maintenance manual is unique to the 800-gallon tank

configuration of the models listed above. 422 units are involved in this campaign.

Production Dates: JUL 31, 2017 - NOV 22, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2018-2021 McLaughlin VX30

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: Using various manufacturing documents, research was conducted to determine the

population of vacuum excavators affected by incorrect lug nut torque value listed in the operator's and maintenance manual. This incorrect lug nut torque value listed in

the operator's and maintenance manual is unique to the 800-gallon tank

configuration of the models listed above. 422 units are involved in this campaign.

Production Dates: JUL 31, 2017 - NOV 22, 2021

VIN Range 1 : Begin : 7HWY202F0JG005029 End : 7HWY202FTMG005120 ✓ Not sequential

Vehicle 3: 2018-2019 McLaughlin VX30G

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: Using various manufacturing documents, research was conducted to determine the

population of vacuum excavators affected by incorrect lug nut torque value listed in the operator's and maintenance manual. This incorrect lug nut torque value listed in

the operator's and maintenance manual is unique to the 800-gallon tank

configuration of the models listed above. 422 units are involved in this campaign.

Production Dates: JUL 31, 2017 - NOV 22, 2021

VIN Range 1: Begin: 7HW1192J6JG005002 End: 7HW1192J1KG005040 ✓ Not sequential

Vehicle 4: 2018-2022 McLaughlin VX50

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Using various manufacturing documents, research was conducted to determine the

population of vacuum excavators affected by incorrect lug nut torque value listed in the operator's and maintenance manual. This incorrect lug nut torque value listed in

the operator's and maintenance manual is unique to the 800-gallon tank

configuration of the models listed above. 422 units are involved in this campaign.

Production Dates: JUL 31, 2017 - NOV 22, 2021

VIN Range 1: Begin: 7HW4192M5JG005001 End: 7HW4212MXLG005559 ✓ Not sequential

Vehicle 5: 2018-2022 Vermeer VX50

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Using various manufacturing documents, research was conducted to determine the

population of vacuum excavators affected by incorrect lug nut torque value listed in the operator's and maintenance manual. This incorrect lug nut torque value listed in

the operator's and maintenance manual is unique to the 800-gallon tank

configuration of the models listed above. 422 units are involved in this campaign.

Production Dates: JUL 31, 2017 - NOV 22, 2021

VIN Range 1: Begin: 1MV4212MAMG010012 End: 1MV4212MVNG010236 ✓ Not sequential

#### **Description of Defect:**

Description of the Defect: Incorrect lug nut torque value was listed in the VX30, VX30G and VX50

operator's and maintenance manuals for affected machines. The lug nut torque listed is a lower value (120 ft-lbs) than recommended by the axle manufacturer

(210 ft-lbs). Lug nuts on affected machines were torqued properly in

production prior to shipment from manufacturer.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Incorrect lug nut torque may cause wheel lug nuts to loosen. This may

increase the risk of wheel loss and the risk of a crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

### **Involved Components:**

Component Name 1: NR

Component Description: NR

Component Part Number: NR

### **Supplier Identification:**

#### **Component Manufacturer**

Name: Vermeer MV Solutions, Inc.

Address: 7835 Augusta Rd

Piedmont South Carolina 29673

**Country: United States** 

#### **Chronology:**

November 9, 2021: Vermeer Corporation received communication from a Vermeer dealer that the VX30, VX30G and VX50 vacuum excavator trailer operator's and maintenance manual contained a possible incorrect lug nut torque value.

November 16, 2021: Vermeer Corporation confirmed the torque value was listed incorrectly for the VX30, VX30G and VX50 vacuum excavator trailer 800-gallon configuration in the operator's and maintenance manual.

Determination was made to start product safety recall.

## **Description of Remedy:**

Description of Remedy Program: Vermeer MV Solutions, Inc. will prepare field remedy kits which will

include replacement updated operator's and maintenance manual to resolve the identified issue. These field remedy kits will be ordered by Vermeer dealers. Upon receipt of field remedy kit warranty claim, dealers will be reimbursed by Vermeer MV Solutions for the associated kit's cost. Registered machine owners will be notified of the potential safety risk and available field remedy kit by letter according to the product database records maintained by Vermeer Corporation on behalf of Vermeer MV Solutions. Vermeer Corporation will administer this campaign on behalf of

Vermeer MV Solutions, Inc., its subsidiary.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: Dealer notifications will begin 06-January-2022 via publication of service

bulletin with sample copy of owner letter, as well as kit instructions, via factory-to-dealer secure website. On same date, reports will be emailed to affected dealers with list of affected machines according to registration ownership located within their area of responsibility. Owner notification letters will be sent by Vermeer Corporation, on behalf of Vermeer MV Solutions, Inc., on 20-January-2022 with translated letters where

Solutions, Inc., on 20-January-2022 with translated letters wh

necessary for their affected units.

Planned Dealer Notification Date: JAN 06, 2022 - JAN 06, 2022

Planned Owner Notification Date : JAN 20, 2022 - JAN 20, 2022

\* NR - Not Reported