

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6064
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 1, 2022

Subject: Rear Suspension Toe Link Safety Recalls
Rear Suspension Toe Link May Break
Revised Buick LaCrosse Labor Time in Warranty Information Table

Models: 2010 – 2013 Buick LaCrosse
2012 – 2013 Buick Regal
2013 Chevrolet Malibu

To: All General Motors Dealers

Bulletins N202308930, N212330130 and N212346640 are being revised to update the Warranty Information table for the Buick LaCrosse only. The Labor Time currently published is for the AWD Buick LaCrosse which requires the fuel tank to be lowered to replace the rear suspension toe links. Since the Buick Lacrosse vehicles included in these recalls are **only FWD**, which do not require the lowering of the fuel tank, the labor time is being corrected from 2.6 hrs. to 1.4 hrs. to be common with the labor time for the Buick Regal and Chevrolet Malibu.

The revision to the labor time is effective today, March 1st, 2022. Any job cards opened on or after March 1st, 2022 will be subject to the corrected labor time of 1.4 hours. The Adjust Link Replacement in the Buick LaCrosse Labor Time Guide will also be revised to reflect the same correction, effective March 1st.

This information was previously communicated in GlobalConnect message GCUS-3-2420 sent on February 3, 2022.

We apologize for the error and any inconvenience caused by this labor time correction.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS