



IMPORTANT SAFETY RECALL

AUTOCAR, LLC SAFETY RECALL ACX-2101 NHTSA RECALL NO. 21V030

March 2021

TO: U.S. Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect, which relates to motor vehicle safety, exists in 3196, 2018-2021 model year Xpeditor chassis manufactured between September 9, 2017 and July 28, 2020 with non-sequential serial numbers between 224486 and 234305 accordingly, a recall to address this issue is being initiated effective March 25, 2021.

MODELS Autocar Xpeditor MY 2018-2021
AFFECTED:

COMPONENTS
AFFECTED: Seat Belt Wiring Harness May Chafe

SAFETY DEFECTS
AND POTENTIAL
RISKS: The seat belt wiring harness routing may be too close to the seat mechanism, if the harness becomes chafed and short circuits, the circuit protection fuse will open, the engine will shut off and not restart, increasing the risk of a crash, personal injury or property damage.

REPAIR
REQUIRED: The seat belt wiring will be routed and secured clear of the seat mechanism at no charge to the owner.

REPAIR
AVAILABLE: VIN profiles in the Autocar Warranty System will be updated to show the open recall on March 25, 2021 and a spreadsheet of the affected VINs will be available in the Warranty system.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000