
Next Unread Message

View Message



April 05, 2021

Re: 2021 CBR1000RR-R (SP) STOP SALE NOTICE - REAR CUSHION CONNECTING PLATE

Dear Honda Dealer:

Honda is issuing a Stop Sale Notice for **CERTAIN** 2021 CBR1000RR-R (SP) motorcycles to inspect the rear cushion connecting plate. It is possible this part was installed in the wrong direction at the factory. An incorrectly installed part may cause the cushion connecting plate to break, increasing the risk of a crash or injury.

Effective immediately, you MUST NOT SELL any affected NEW or USED 2021 CBR1000RR-R (SP) motorcycle until it is inspected, and repaired (if needed), according to the associated Service Bulletin.

AFFECTED UNITS:

The 2021 CBR1000RR-R (SP) motorcycles included in the VIN range below are affected by the Stop Sale.

VIN	
FROM	ТО
JH2SC82B*LK000020	JH2SC821*MK000092

To manage your affected inventory, use eResponsibility Report.

SERVICE BULLETIN

Service Bulletin CBR1000RR-R #1, which includes all information to perform this repair will be available April 09, 2021.

PARTS INFORMATION

If it is determined a motorcycle needs a repair (by inspection outlined in the Service Bulletin), contact TechLine via TechLine Connect for further instruction and parts information.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected 2021 CBR1000RR-R (SP) motorcycles in May 2021. Customers will be informed their motorcycle may be affected by a safety related defect and will be advised to make an appointment with an authorized Honda powersports dealer for inspection and, if necessary, repair.

Make sure all departments in your dealership are aware of this action.

If you have any questions, please contact AHM TechLine through TechLine Connect on iN.

Sincerely,

American Honda Motor Co., Inc.

Powersports Division

MTB 17719 (2103)