

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6040
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 27, 2022

Subject: REVISION: Safety Recall - N212340980-04
Rear Toe Link Separation
Revised Service Procedure Alignment Settings

Models: 2010-2016 Cadillac SRX
2011-2012 Saab 9-4x

To: All General Motors Dealers

The service procedure Alignment Settings has been updated in this bulletin.
Please discard all previous copies of N212340980.

Important Reminders

Saab vehicles should be repaired by the GM dealer under this recall. Use the appropriate model year Cadillac SRX repair procedure and specifications.
They will not be serviced at official Saab Service Centers.

Question and Answer Document (Q&A)

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS