

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS5995  
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 2, 2021

Subject: REVISION: Safety Recall - N212340980-03  
Rear Toe Link Separation  
Revised Warranty and Service Procedure

Models: 2010-2016 Cadillac SRX  
2011-2012 Saab 9-4x

To: All General Motors Dealers

This bulletin has been updated in the warranty and service procedure sections.  
Please discard all previous copies of N212340980.

**Important Reminders**

**Saab vehicles should be repaired by the GM dealer under this recall. Use the appropriate model year Cadillac SRX repair procedure and specifications. They will not be serviced at official Saab Service Centers.**

**Question and Answer Document (Q&A)**

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS