

DEALER NAME Address here City, State, ZIP here Country here

Tuesday, June 29, 2021

From: From: Len McDougall, Head of Sales and Service, Roadtrek Inc.

RE: Notice of Recall: NHTSA 21V477 Incorrect CO/LP Detector

Roadtrek Inc., is recalling certain model year 2020 to 2021 Roadtrek Zion, Zion SRT. Play and Slumber models built on the Dodge RAM ProMaster Chassis and SS Agile model built on the Mercedes Benz Sprinter chassis manufactured from September 1, 2020, through February 26, 2021. A small number of the incorrect model CO/LP detectors were installed on shipped vehicles. The incorrect detector is marked as "Safe-T-Alert RV Propane Alarm" rather than the correct detector which is marked "Safe-T-Alert RV Carbon Monoxide / Propane Gas Detector".

Owners are asked to check the CO/LP detector that is installed in their vehicle and fill out the attached **Corrective Action Completion form** attached and send it to Roadtrek Inc. Owners that report having the incorrect "**Safe-T-Alert RV Propane Alarms**" in their vehicle will then have an additional **Carbon Monoxide detector** shipped to them at no cost to install on their vehicle.

If you need assistance completing the inspection of your CO/LP detector, please contact Roadtrek Inc., Roadtrek Dealer Service at 1-888-762-3873 or by e-mail at dealersupport@roadtrekinc.com

We regret any inconvenience this action may cause