# \* \* TECHNICAL INFORMATION NOTICE \* \*

anagers,
SAFETY RECALL CAMPAIGN

#### 

#### AFFECTED VEHICLES: Certain 2022 Outlander vehicles


#### PURPOSE

MMNA would like to remind all dealers and technicians of the importance of proper removal and installation of the pretensioner connector when replacing a seatbelt on a 2022 Outlander for Recall SR-21-007. Failure to follow proper procedure and applying unnecessary force will damage the connectors. The connectors are not available as a service part and replacement of the entire floor harness will be required. Please use the instructions below for proper removal and installation of the pretensioner connector.

### <u>MMNA will perform an inspection and analysis of warranty part returns. If the pretensioner</u> <u>connector is found to be damaged the returned wiring harness will be reviewed and potentially</u> <u>processed for charge back to dealers.</u>

#### Pretensioner connector removal/install Process


1. Removal process to avoid damage.




2. Removal and inspection of connector.








3. Proper installation and inspection.





## **IMPORTANT**

Affected new or used inventory vehicles must be repaired before the vehicle is sold/delivered. Dealers must check their inventory vehicles' VINs on the Warranty Superscreen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to sell/deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification